Cathy Rossetti 21 August 2006 Summer 2006 Independent Study (Asst. Prof - Amy Hillier)

Table of Contents

1	INTRODUCTION	3
	1.1 THE STUDY	3
2	DATA SOURCES	3
	 2.1 FIRE INSURANCE SURVEYS 2.2 FIRE INSURANCE MAPS 	
3	DATA MANAGEMENT	5
	3.1 DEVELOPMENT	7 7 <i>7</i>
4	NEXT STEPS	9
5	ADDITIONS & EXTENSIONS 1	0
	5.1 Data	
6	ADVICE & LESSONS LEARNED 1	.1
	6.1 DATA LIMITATIONS	1 1 2 3 3
7	SUMMARY 1	4
8	APPENDIX A – PROPERTY REPORT 1	5

1 Introduction

1.1 The Study

The research project *Mapping the Du Bois Philadelphia Negro* investigates the foot survey conducted by W.E.B. Du Bois for his 1899 publication *The Philadelphia Negro*.¹ The primary focus is to gain an understanding of the socio-economic factors at play in the city at the time and apply GIS to the analysis and dissemination of that information. While the value of an investigation into the built world of the time is not initially obvious, a view from an Historic Preservation perspective can contribute greatly to an understanding of the overall picture.

1.2 The Role of Preservation

The aim of Historic Preservation has often been to evoke a feeling or image of a place at a significant point or points in its past. The Lower East Side Tenement Museum in New York City² is one good example. By restoring several different apartments in a single tenement building to various points in history, a tangible picture of the evolution of a city's immigrant population is presented. When a single illustrative structure is unavailable, as is the case in the Du Bois study, the same principles can be applied on a larger scale using many buildings. Given that a complete reconstruction of the study area is neither a study goal nor a viable alternative, GIS and 3D modeling can enable a virtual restoration that allows similar opportunity for investigation.

1.3 The Basis for Investigation

Understanding the socio-economic conditions of a place or a people requires a wide variety of information types. If we begin with the premise that Historic Preservation can provide historical perspective, architectural records must be considered important among those information types. Architectural records can include maps, surveys, and photographs, among other things. Taken by themselves, these documents provide valuable information about living conditions. For example, they can be used to differentiate wealthy areas from poor, thinly developed blocks from densely populated, and residential areas from industrial. By extension, combining architectural records with other historical data allows hypotheses to be drawn about the motivations and lives of the people who lived, worked and owned property in a target area.

2 Data Sources

For the purposes of prototyping the value of architectural history to the Du Bois study, a subsection of the overall study area was defined. For this area, between 7th and 8th Streets and Addison and Rodman Streets, a simple MS Access database was created to house the data. Intended as a testing ground to demonstrate the variety of data available for the City of Philadelphia, it can be updated to include additional records and expanded to enable

¹ See W.E.B. Du Bois, *The Philadelphia Negro* (University of Pennsylvania Press, 1996).

² See their website for further information on the National Trust property - <u>http://www.tenement.org/</u>.

entry and analysis of additional information types. Key data source types are fire insurance policies / surveys for individual properties and fire insurance maps of the city.

2.1 Fire Insurance Surveys

The primary source of data collected for the study was fire insurance surveys pulled from the archives at the Pennsylvania Historical Society. Insurance records are available from a variety of 18th and 19th century insurers. These include Mutual Assurance, Philadelphia Contributionship, Franklin Fire Insurance, and Pennsylvania Fire.

Insurance policies were created for property owners in Philadelphia, be they individuals or businesses. Until the early 20th century, these documents were written longhand – a practice that generated both lovely calligraphy and significant legibility (see Transcription). Surveys were captured in prose and although the type of information captured varies by insurer, policies frequently documented the following: address, policy owner(s), structure dimensions, materials, building use, floor-plans, interior and exterior style and condition descriptions, and miscellaneous notes captured by the surveyors. Very occasionally, photographs were also included in the more recent surveys.

Oftentimes, insurers would resurvey a property one or more times during the life of a policy, with these resurveys typically documented as handwritten notes in the margins of the original document. These amendments are rarely made in the exhaustive detail of the original. It is not unusual for a property to have had policies with several different insurers over time. In such cases, the later policy includes a new detailed survey of the property.

Insurance policies provide a valuable glimpse into each property that is otherwise unavailable in such detail on such a broad scale in Philadelphia's architectural records. While finding a complete set of insurance surveys for every property on a block is unlikely, when aggregated, the existing survey data can be used to paint a general picture of a street or neighborhood.

2.2 Fire Insurance Maps

Fire insurance maps from the Free Library of Philadelphia also provided a valuable resource to the study. These maps are bound in enormous volumes, typically with two to three blocks mapped on each page. Although several different companies and individual map-makers are represented in the Free Library's map collections, G.W. Bromley & Co. and Hexamer & Lochner are the most prominent providers of the city's fire insurance maps.

For the purposes of the Du Bois study, the 1896 G.W. Bromley & Co. map of the 7th Ward of the City of Philadelphia provided the most useful and timely information.³ Each block in the target area was digitally photographed. After the images of each page were assembled into a single electronic map, they were georectified in ArcMap to show the relationship to the modern day parcels. The resulting digital map is the basis for the

³ <u>Atlas of the City of Philadelphia</u> (Philadelphia, G.W. Bromley & Co., 1896) Vol. 2, Plates 10-11.

creation of an historic parcel layer. The parcel layer can then serve as the framework onto which detailed property and occupant data can be hung, allowing for a great level of specificity in the eventual analysis stage.



Figure 1 - Composite photograph of the target study area in the 1896 Bromley map overlaid with modern parcels outlined in red.

In addition to parcel shape, size and location, the 1896 Bromley provides valuable information on the building materials and address numbers for the study area. While not typical of all Bromley's, the 1896 edition also identifies property owners, which can be cross-referenced with survey and insurance data.

3 Data Management

3.1 Development

As was mentioned earlier, the database created for the Du Bois study was built as a prototype. Though it is not fully matured, its current form does provide sufficient

functionality to aid preliminary analysis. MS Access was chosen as the database platform because it is readily available, comparatively simple to develop and maintain and has minimal hardware platform requirements.

The first steps in the database's design were to carefully review the available data and begin to understand how that data was likely to be used. That is, it was necessary to understand what kinds of questions were likely to be asked of the database. Would it be used simply to understand gross trends, or were individual properties to be interrogated? Was the data to be used solely for reporting, or was 3D modeling important? If the data was to be used for virtual modeling, specifically which elements of each property were most important? The answers to these and many other questions led to the simple database design described in the Data Model section below.

At a high level, the database captures data in three primary categories or tables. These include data about each property, buildings on that property, and floors in each building. Defining the data elements to be captured within those tables was an evolutionary process, developing as patterns emerged in the data. As common data elements surfaced across multiple policies, it was necessary to continually re-evaluate whether those data elements were of sufficient value to warrant a change to the database. By breaking the data down to a greater level of granularity, new questions could be posed, but changing the database meant moving existing data to the new format. In the future, greater familiarity with the data sources and a more thorough initial analysis of the data needs will all but eliminate this iterative process.

Once the data elements and tables were defined and built, a data entry mechanism was required. Simple MS Access data entry forms were created for each of the tables. Wherever possible, drop-down boxes were built into the database to ensure consistency of data. Drop-down boxes restrict the data captured to valid options, mitigating variation between data entry staff and eliminating typographical errors in those fields. For example, by limiting the choice of insurance company names to only those included in this study, duplicate entry resulting from misspellings is eliminated and data integrity is maintained.

Drop-down boxes are populated via four Lookup Tables that contain the valid data options for each drop-down box. Further development of the database might include the addition of simple data entry screens to facilitate addition of acceptable values by a system administrator into the drop-down boxes.

Because reporting requirements at this stage are rudimentary, only one report was created which provides broad access to the data. The Property Report provides complete contents of the database organized by address.⁴

⁴ See Appendix A – Property Report.

3.2 Data Entry

Once development was complete, data entry began in earnest. Because the insurance policies are handwritten, data entry is not a simple exercise. A variety of limitations exist and these are outlined more fully in the Data Limitations section below. The researcher must read and understand the content before parsing it into the various data entry fields available. Continuity of entry across researchers and over time is important to maintaining data integrity, as is a firm understanding of the language of property surveys in 18th, 19th and early 20th century Philadelphia.

Estimating data entry time for each policy is difficult, varying with the size or complexity of the property, clarity of the handwriting, detail of the descriptions, and experience of the researcher. However, once proficiency is achieved, transcription into the existing database generally takes 40 to 50 minutes per survey. Later surveys documented by the Philadelphia Contributionship during the early 20th century are hand recorded onto standard preprinted forms, greatly simplifying both the data captured and the transcription effort. Because these are also typically much less detailed than policies produced by the other, earlier insurers, transcription takes only 5 to 10 minutes per policy.

To date, for the study area between 7th and 8th Streets and Addison and Rodman Streets, 71 insurance records have been transcribed. Another 10 have been identified for transcription. Within these records, 120 buildings have been recorded and 383 floors documented.

3.3 Data Model

The existing data model is described below. For a proper implementation on a larger scale, more careful analysis is required. Fortunately, data volume is quite limited at present, simplifying any future data migration efforts.

	Insurance_Rec	ords_v3_Prop	erty	
	Field Name	Data Type	Field Description	
Key	Property_ID	Autonumber	Long Integer	Automatically generated key attribute
	Add_Num	Text	255	Address number
	Street_Name	Text	255	Street Name (most recent name as listed on policy) (selected from Drop-down list box)
	Pol_Num	Text	255	Policy number
	Insur_Type	Text	255	Insurance company name (selected from Drop-down list box)
	Owner_Name	Text	255	Policy Owner / Property Owner name
	Floorplan	Yes/No		Is a floorplan drawing included with the policy? Yes or No
	Pol_Date	Date/Time		Date policy first underwritten
	Notes	Memo		Text included on policy that is not otherwise captured in another field

3.3.1 Primary Tables

	Field Name	Data Type	Field Size	Field Description
Key	Buildings_ID	Autonumber	Long Integer	Automatically generated key attribute
	Property_ID	Number	Long Integer	Property Table key attribute
	Num_Floors	Number	Long Integer	Number of floors in the specified building (selected from Drop-down list box)
	Bldg_Material	Text	255	Primary building material (selected from Drop-down list box)
	Bldg_Dim	Text	255	Building dimensions
	Bldg_Type	Text	255	Primary building use (selected from Drop- down list box)
	Notes	Memo		Text included on policy that is not otherwise captured in another field (Made redundant in favor of Notes attribute at Property level, so not included on data entry form)

	Insurance_Rec	ords_v3_Floo	rs	
	Field Name	Data Type	Field Size	Field Description
Key	Floors_ID	Autonumber	Long Integer	Automatically generated key attribute
	Buildings_ID	Number	Long Integer	Buildings Table key attribute
	Property_ID	Number	Long Integer	Property Table key attribute
	Floor	Text	255	Floor number or name (selected from Drop- down list box)
	Bldg_Desc	Memo		Description of the floor's attributes

3.3.2 Lookup Tables

	Bldg_Use			
	Field Name	Data Type	Field Size	Field Description
Key	ID	Autonumber	Long Integer	Automatically generated key attribute
	Property_Type	Text	50	Primary use of the building

	Insurance_Typ	es		
	Field Name	Data Type	Field Size	Field Description
Key	ID	Autonumber	Long Integer	Automatically generated key attribute
	Insurer	Text	50	Name of insurer providing the policy

	Level			
	Field Name	Data Type	Field Size	Field Description
Key	ID	Autonumber	Long Integer	Automatically generated key attribute
	Bldg_Level	Text	50	Floor / level name or number

	Material			
	Field Name	Data Type	Field Size	Field Description
Key	ID	Autonumber	Long Integer	Automatically generated key attribute
	Material	Text	50	Primary building material

Streets			
Field Name	Data Type	Field Size	Field Description

Key	ID	Autonumber	Long Integer	Automatically generated key attribute
	Streets	Text	255	Street direction, name and type

4 Next Steps

Now that a significant sampling of data is available for a portion of the Du Bois study area, serious analysis of the results can begin. An obvious place to begin is a thorough comparison of the areas specifically described by Du Bois with the physical records that remain.

In his research, Du Bois discusses the "Negro slums", particularly in the vicinity of Seventh and Lombard Streets and how they changed during the 19th century. They were at the nexus of the abolitionist riots in the early part of the century. It is interesting now to review the architectural record to see what else can be learned about the neighborhood both at the time of the riots and at the time of his foot survey. Were the homes plain or richly detailed? Were there descriptions of their state of repair? What changes are seen in surveys repeated over time? This might give some idea of their original occupants and changing economic fortunes of the area.

Occasionally, a surveyor's own comments are more interesting than the architectural details of the buildings themselves. For example, a surveyor for the Philadelphia Contributionship noted the following on his 1922 assessment of Louis J. Gandolfo's property at 427 S. 8th Street: "The housekeeping in all of the occupied apartments is of the usual negro untidy type." This would seem to support Du Bois's assessment of the neighborhood several years before, where he described 7th and Lombard as "the worst Negro slums of the city."⁵ It will be interesting to further validate this and other of Du Bois' assumptions regarding the class of people in the area and the type of rents commanded by the local landlords.

Combining insurance policy owner information with occupant data collected from census records can raise interesting implications about ownership patterns. And, while not typical of all G.W. Bromley & Co. maps, the 1896 edition identifies property owners. This provides yet another data point to cross-reference property ownership with census and insurance data.

Other questions worth asking include: Were the residents of a street predominantly Black or White? How was the condition assessed at each property? Did the white residents live in better quality housing than blacks? Did the houses or apartments have bathrooms? Running water? In some cases along Lombard Row, it was noted that plaster was falling from the ceilings and walls of the "Colored Dwellings" there and the properties were labeled a bad insurance risk. Who owned them and who lived there? What were the trends in non-resident ownership? What were the trends in immigration and how did they coincide with condition of the properties?

⁵ *The Philadelphia Negro*, 1996 edition, pg. 58.

The remaining step will be to hang all of the data gathered from the insurance surveys and detailed in the database onto the parcel layer built from the Bromley map. By combining parcel data with building information (e.g., building materials, dimensions, style, etc.), 3 dimensional models of the streetscape can be built. When fully developed, a digital 3D model can approximate a virtual 'restoration' of a large area at minimal cost, contributing toward one of the Preservation aims discussed earlier - to evoke a feeling or image of a place at a significant point or points in its past. Even without the 3D model, the parcel layer and its associated data can be Web enabled to allow broad access to the information.

5 Additions & Extensions

5.1 Data

The data captured for the purposes of this pilot was limited to maps and insurance records. Further valuable data is yet to be gathered from a variety of additional data sources.

Philadelphia City Directories were published throughout the 18th and 19th centuries in Philadelphia. While several different publications exist, these directories typically contain the names, homes and / or workplaces of the city's residents. Tracing names through time can be useful to locate home addresses and workplaces of non-resident tenement landlords in the study area. It is also helpful in identifying migration patterns of residents. Finally, it can help clarify questions arising from a comparison between property owner names recorded on insurance policies, maps and the census. Additional questions that might be answered include: Were there primarily resident or non-resident owners? Where did residents work in relation to their homes? When residents moved in, were they coming from more or less economically advantaged areas? When residents left, where did they go next?

Additional buildings data is waiting to be found in a variety of places, including the records of the Octavia Hill Association and the City Archives. As a prominent landowner in the study area in operation continuously since the late 19th century, the Octavia Hill Association maintained extensive records, including property records, reports, and legal correspondence and published articles. Now housed in the Urban Archives at Temple University are Octavia Hill Association manuscripts and photographs dating between 1880 and 1970. These property and ownership records can help fill the gaps where specific insurance surveys left off, telling us more about the specific buildings.⁶ The collection can also help answer questions about tenement house and related legislative policies and movements afoot at the turn of the century.

The Philadelphia City Archives holds deed and mortgage information for the city. While conducting research there is a painstaking process, mortgage property transaction information can be used to gauge the economic health of an area. It can help answer the

⁶ Octavia Hill properties tended to be surveyed as a group by insurers and, therefore, less detail was captured on individual units.

questions: Who is buying / selling there and when? When were the boom / bust years? What were the trends in non-resident ownership?

Further property information is available at the Philadelphia Historical Commission. Their records include, but are not limited to, files on properties listed on the Philadelphia Register of Historic Places as well as those listed on or eligible for the National Historic Register. While the records maintained on each property vary, they often contain chains of title, photographs, and fire insurance surveys. Other likely sources include neighborhood associations and neighborhood historical commissions. In each of these cases, records may help plug the gaps in insurance record coverage and may provide details that supplement existing data.

5.2 Analysis

Concurrent research within the *Mapping the Du Bois Philadelphia Negro* Project may also provide interesting data for integration with the buildings data. It could be useful to look for patterns in businesses in the area (e.g., caterers, restaurants, tradesmen, etc.). Who owned them? For Black-owned businesses, what comparisons can be made about the types of businesses, size and condition or property and longevity on site? It would also be interesting to ask which properties were in the worst condition and what correlation can be made regarding rates of illness with these properties.

6 Advice & Lessons Learned

6.1 Data Limitations

6.1.1 Gaps

While the available insurance data is a rich resource, it does have limitations. Data gaps are common because records are not available for every property in the city. Similarly, records that do exist span hundreds of years of Philadelphia's history. It is unlikely that records of a consistent date exist for an entire block. The impact of these gaps is a limitation on the types of generalizations and hypotheses that can be made from the data. Investigation into additional data sources as described in the Additions & Extensions section above will help close this gap.

6.1.2 Transcription

Data transcription errors are inevitable when dealing with historic records. Certainly, the human element is involved in such a manual process, but several other factors are also at play. All of the 18th, 19th and early 20th century records were written out longhand. Between the cryptic handwriting and evolution of the written alphabet over time, legibility can be difficult. With some of the earliest records captured in caustic inks on parchment, poor document preservation further hinders legibility.

Furthermore, surveys were captured in prose, with survey styles and order and content of information varying across surveyor and over time. Continuity between data entry staff can lead to variations in data integrity. This also makes field restrictions based on a standard set of characteristics, difficult. That is, if every insurer indicated the number,

size and style of windows on each façade in the same way, drop-down boxes might be used or data entry fields might be restricted to numeric or fixed length text fields. As it stands, this type of information is inconsistently and incompletely recorded by insurers and a specific need for a separation of this data has not been identified. For the moment, it is captured in a 255 character length text field in the database along with other various building notes.

Assuming further validation and restriction of data entry fields cannot by conducted within the database, the logical step is to ensure the consistency of researchers' understanding and interpretation of the data. Development and use of a data dictionary that includes the architectural and descriptive vocabulary of the day can help researchers agree a consistent pattern for data entry, and achieve a common understanding of terminology, thereby improving recognition of terms in handwritten text.

6.1.3 Continuity

Adding to the data transcription woes is the evolution of the use of language over time. The use of punctuation, grammar, and spelling appears to have been poorly standardized throughout the 18th and 19th centuries. For example, the word "plastered" (to mean the applied composition of lime, water, and sand, used as a wall or ceiling coating) is spelled variously as "plastered", "plaisterd", "plaister'd", or simply "plaister", with no past tense indicated. This varies across time as well as from surveyor to surveyor.⁷ To add further complexity, the earliest records contain a cursive "s" that resembles an "f". Not only does this create difficulty with document comprehension, but it also highlights the importance of identifying a standard data dictionary at the outset of data capture. Which spelling will be used for the collected data? Will non-standard entries throw off future analysis or calculation of, for example, building materials in 19th century Philadelphia?

The English language itself has changed over time, with some terms no longer in use. Commonly found in early Philadelphia's parlours were "washboards" and "surbase" (or "sub base"). Today these are known as "wainscoting" and "baseboards", respectively. Similarly, standard architectural features have come and gone with changes in the aesthetic and functional requirements of residents through the years. For example, ash holes for coal or wood stoves are no longer in common use. Combined with the aforementioned legibility issues, documentation of an 'ash hole' or a 'chimney breast' in a property is likely to cause raised eyebrows among researchers at first glance. Until these terms are understood, documented and standardized by the research team, variation in data captured and errors or gaps in transcription remain inevitable. Once again, the data dictionary can prove most helpful.

Address numbers varied across time, as did street names. With the insurance records, oftentimes there was no street address recorded at all. The record will simply state the distance and direction from a nearby intersection. This situation typically occurs in the earliest records. Of course, these older records are also the most likely to reference

⁷ As an aside, one wonders whether limited literacy, standardized education or access to printed material contributed to the striking lack of consistency in spelling, grammar and punctuation throughout the 18th and 19th centuries.

outdated street names and some of these might have changed two or three times. So, for example, you might find a policy that identifies a structure as located at "...No. 48 on the North side of Mary, between Seventh & Eighth Streets" or worse yet, "...on the north side of Bradford Alley commencing about 90 feet west of 7th Street." In either case, additional work is required to specifically identify a property's current address number and street name. This can be done by cross-referencing the survey ownership records with the census, City Directories, early maps or other sources described above.

6.2 Data Management Changes

6.2.1 Technical Platform

MS Access was chosen as the database environment for reasons of cost, simplicity of implementation, and ease of maintenance. The price for this simplicity is lack of flexibility and limited functionality. For a more scalable and robust implementation, Oracle is recommended. This more professional environment is significantly more flexible than MS Access, allowing more detailed analysis and reporting. It does have associated consequences, however. It is more costly to operate, with greater license costs and hardware requirements. Similarly, development and ongoing hosting, maintenance and support require greater expertise, further adding to the cost. These added costs would need to be evaluated and weighed carefully against the data analysis and storage requirements and anticipated benefits before proceeding with a migration to a new platform.

Currently, the data entry interface is a collection of MS Access forms. Very little data checking is enabled. As was mentioned in the Advice & Lessons Learned section, with each surveyor and insurer capturing data differently, it is not possible to restrict many fields based on a standard set of characteristics. Both the flexibility of the tool and expertise of the developer were limiting factors as well. Movement to an Oracle environment would allow for optimization of the interface to speed data entry and improve data integrity.

6.2.2 Data Model

Movement to Oracle would also provide an opportunity to revisit the data model. As new data sources are included, additional data types will need to be captured. This will be a factor leading to a revision of the data model and will trigger an analysis of the relationships between data elements in order to ensure optimal performance.

To begin, it will be important to understand the data sources and how the data will be used. What systems will use it and what types of queries will be made. Consistency with the data standards used by other systems may be important, as is the level of specificity required. For example, when capturing an address, is it necessary to break that address into each possible component (e.g., number, number suffix, street direction, street name, and street type), or will simple number and street name fields suffice? For a small study area or for a project with limited integration to other databases, the simplest approach may be enough, but these sorts of questions must be asked of each data element captured.

Regarding the data elements captured, it is a good opportunity to revisit the existing elements. In the existing model, if a street name has changed over time, only the most recent name is captured. Earlier names or addresses are noted in the main text description field for the property. Depending on the information need, there may be value in populating a separate table with alternate street names. As was discussed in the Advice & Lessons Learned section above, a need has yet to be identified to specifically break out the number of windows per façade along with their measurements. Would it be helpful to the 3D modeling effort in the future? The last obvious element for consideration involves resurveys of existing properties. Currently, the resurvey data is included alongside the original data within the text description for each property. A more flexible option would be to include resurveys separately from the original description. This will enable better access to property information by survey date.

7 Summary

As often happens, conducting research raises more questions than it answers. That this is true in this case validates the initial premise that considerable insight can be gained into a society via a careful review of the built environment over time. Even with the small volume of data gathered to date from a limited range of sources, many questions can be answered through further analysis. Patterns emerging from the map and insurance policies can be correlated with other historical data and even with Du Bois' own words. Still other questions await the capture of data from additional sources.

In order to make the most effective use of the information available, it is important to clearly understand the questions to be asked. Once they are defined, the data requirements can be understood, their relationships defined, and a thoughtful approach to capture, storage and analysis planned out. Future work should begin with a careful review of the questions to be answered. From there, identification of the most important data sources and mining of that data can begin. A properly designed data map and solid database platform will then allow for flexibility and scalability as the project progresses and grows. Regardless of the next steps taken, the initial prototype discussed here demonstrates clearly that even before a virtual 3D model is complete, a view from an Historic Preservation perspective can contribute greatly to an understanding of the overall picture.

8 Appendix A – Property Report *Insurance Records Report v3 - All Properties*

Policy #	4918	Insurer	Pennsylvania Fire	Policy Date	8/8/1845	Property ID 1
Address	401		S. 8th Street			Floorplan
Owner Name	Wm E Hacker	r				
Notes	Situated on the modern style.	SE corner of	8th and Little Pine Streets betwee	en Pine and Lombard St	reets having a Piazza an	d a three story Back Building all built in
	Policy cancelle	ed February (?) 13, 1907			
Building Type	Residence		Building Material	Brick		Building ID 1
Dimensions	12'x35'		# of Floors 3			
Floor	# F	Floor_ID	Building Description			
1	1		The first story main house 11'9" clear I transom sash having a marble lintel ov panelled door. Stucco cornice in the er glass 11x20 inches. One window back under the windows the windows panel panelled, Carolina pine floors and a ce	ver it. A vestibule at the fror ntry and vestibule. The part a. All have panelled shutters led and 8 inch sheeting wit	nt door having sidelights an lor has a white Italian marb s. The windows and doors a h a moulding on it. The out	d a square transom sash over it with le mantel and hearth. Two windows the are all trimmed with pilasters dadoes ermost doorway is of 2 inch plank
2	2		hearth in each room and a common cle	oset. Two windows front 12 ed shutters all the sash are	2 by 20 inch glass and Vene double hung the doors and	arble Italian marble mantel with marble etial rolling blind shutters. One window I windows are trimmed with pilasters, 8 I pine foor. Hemlock joist.
3	3		plain handrailing and ballusters and a windows front the glass 12 by 14 inch	closet under at 14 riser Yel es. One window back Vene	low pine steps, hemlock jo etian rolling blinds front and	n a common straight stairway having a ist. Carolina pine floor 8 feet 6 story Two I pannelled shutters back a wood ng trimming to the doors and windows.
Garrett	4		The garrett has two rooms common Ca each front with pediment heads 12 ligh			
Roof	14		'A double pitched roof. Cedar shingles front, Brick eaves. Cornice back comm			t is common strip gutter, wood cornice ted as usual.

Building Type	Piazza	Building Material Brick	Building ID 26
Dimensions	8'x14'	# of Floors 3	
Floor #	Floor_ID	Building Description	
1	81	Contains a side doorway with side lights and a continues mahogany story including 3 windows and a landing with a communication into th	
2	82	The upper flight has 19 risers and a half?? And is lighted by a window	v at each story landing all yellow pine steps.
		There is a private winding stairway at the back of the main stairway of opposite large pantry closet which is in the circular end of the back be	
		Also a dumb waiter closet in the first and second stairs	
3	83	The bath room is in the third story in the circular end partitioned from pantry rooms and bath room similar to those of the back building.	the back building and stairway one window in each of these
Garrett	84		
Building Type	Residence	Building Material Brick	Building ID 41
Dimensions			
	13'x27'	# of Floors 3	
Floor #	13'x27' Floor_ID	# of Floors 3 Building Description	
<i>Floor #</i> 1		,	ghts with glass a pantry closet and dumb waiter hung with
	Floor_ID	Building Description The Back building first story is the kitchen and has two windows 12 lie	ghts with glass a pantry closet and dumb waiter hung with
	Floor_ID	Building Description The Back building first story is the kitchen and has two windows 12 linweights and ??.	ghts with glass a pantry closet and dumb waiter hung with
	Floor_ID	Building Description The Back building first story is the kitchen and has two windows 12 live weights and ??. Carolina pine floor common skirting and plainly finished as usual.	e platform is about 10 feet deep having a ?? railing in front of it

3	113	The third story (9'6"? High) has one room over the dining room a wood mantel 4 windows inclusive bath room 11 by 13 inch glass pannelled shutters and is plainly finished throughout, and all the rooms plastered.
		The bath room in the third story partitioned off at the landing end about 8 by 10 feet ?? From the landing ??
Roof	141	A single pitched roof cedar shingles tin gutters brick eaves.

Policy #	4920	Insurer	Pennsylvania Fire	Policy Date	1/1/1846	Property ID	2
Address	405		S. 8th Street			Floorplan	
Owner Name	Isaac Hacker						
Votes	Situated about 3	38 feet South	from Little Pine Street on the Ea	st side of 8th Street. Bui	lt and finished in mo	odern style.	
	10x12 window	& outside pa	hen has been constructed beneath anel shutters a door S to yard, a da 7'8" high. The dumb waiter in pa	resser with 4 doors 2 drav	wers a cooking range	e and household ?? H	las an enclosed sink
	Cancelled Octo	ber 1, 1903					
Building Type	Residence		Building Material	Brick		Building ID	2
Dimensions	19'x34'		# of Floors 3				
Floor	•# F	loor_ID	Building Description				
1	5		The first story (10'6" ceiling) main hor transom sash having a marble lintel of pannelled door and transom sash ov a white Italian marble mantle and hea shutters. The windows and doors are moulding on it. The entrance door wa center piece and ?? Pannels in the ce	over it a vestibule at the fron er it. Stucco cornice in the e arth. Two windows front with e all trimmed with pilasters o by is of 2 1/2 inch plank pan	t door with a doorway ntry and vestibule. The plate glass 11x20 inch ladoes under the windo	in the entry having side parlour which extends t les. One window back ws pannelled and 8 1/2	lights and a the whole depth has all have pannelled t inch skirting with a
2	6		The second story is 10 feet 6 inches each room and a common closet. Tw by 20 inch glass with pannelled shutt skirting pannelled plank door to each	o windows front 12 by 20 in ers all the sash are double h	ch glass and Venetial r nung. The door and win	olling blind shutters. On dows are trimmed with	e window back 12
3	7		The third story has two rooms and a plain handrails and ballusters and a cinch story clear height. Two windows and pannelled shutters back, a wood trimmings to the door and windows.	loset under it. 14 risers in the front the glass 12 by 14 inc	ne stairs yellow pine ste ches one window back	eps hemlock joists yellow with venetian rolling blir	w pine floors 8 feet 6 ad shutters front
Garrett	8		The garrett has two rooms common each front with pediment heads 12 lig				dormer windows in in

Building Type	Piazza	Building Material Brick	Building ID 27
Dimensions	8'x6'	# of Floors 3	
Floor #	Floor_ID	Building Description	
1	85	The piazza contains a side doorway with side lights and risers in the first story including 3 windows and a landing	a continued Mahogany handrailing stairway with turned ballusters 21 with a communication to the back building.
2	86		d by a window in each story landing all yellow pine steps. There is a private d off with a partition and has 18 risers and is build opposite a large pantry ne closet in each story shelved.
		Also a dumb waiter closet in the first and second stairs.	
3	87	The bath room is in the third story in the circular end par pantry rooms and bath room similar to those of the back	titioned from the back building and stairway, one window in each of these building.
Building Type	Residence	Building Material Brick	Building ID 42
Dimensions	13'x24'	# of Floors 3	
Floor #	Floor_ID	Building Description	
1	114		indows 11 by 14 inch glass a pantry closet and dumb waiter hung with plainly finished as usual. The private stair is opposite the pantry closet.
		Two heating furnaces one front and one back.	
2	115		4 windows including the pantry 11 by 16 inch glass, with pannelled , pilaster architrave 1 1/2 inch plank doors, Carolina pine floor stucco cornice
3	116	The third story has one room over the dining room a woo pannelled shutters and is plainly finished throughout and	od mantel, 4 windows including the bath room, 11 by 13 inch glass , all rooms are plastered.
Roof	143	A single pitched roo cedar shingles Tin gutters. Brick ear	/e.

Building Type	Water Closet	Building Material	Frame	Building ID 52
Dimensions	4'x10'	# of Floors 1		
Floor #	Floor_ID	Building Description		
1	180		the back of the kitchen build against it. The platfor feet of this is enclosed and is used as a water clo h it is enclosed.	

Contributing a	n Historic	Preservation	Perspective to the Mapping the Di	u Bois Philade	lphia Negro Projec	t	
Policy #	63633	Insurer	Franklin Fire Insurance Company	Policy Date	2/18/1885	Property ID	3
Address	428		S. 7th Street			Floorplan	
Owner Name	John J. Wi	ilkinson					
Notes			ng and store with two story high back bui Street, in the Seventh Ward of the City o		e West side of South S	Seventh Street No 4	428 beginning about
	White pine	floorboards, Sc	anthy window frames, panel shutters to f	irst story and Ven	etian to second and th	ird story front build	ding plastered
Building Type	Multi-ı	ıse	Building Material Bri	ck		Building ID	3
Dimensions	13'x14	,	# of Floors 3				
Floor	r #	Floor_ID	Building Description				
1		9	The first story of the first house has a doorwa window with 9 lights 18x24 sash in it and par				
2		10	The second story has a narrow stairway off t front, plain wood mantel, panel doors, 7 ft sto		iding stairs and a closet u	inderneath, 2 12 light	8 by 10 window
3		11	The third story has 2 9 light 8 by 10 windows in rafters, a ?? wiith ledge, door back opens			ront and 6 ft 8in high	back, ceiling partly
Roof		144	Single pitch tin roof, brick eave and tin condu	ictors front.			
Building Type	Reside	nce	Building Material Bri	ck		Building ID	28
Dimensions	9'x20'		# of Floors 2				
Floor	r #	Floor_ID	Building Description				
1		88	The back building first story has a stairway o underneath, a doorway into yard with 6 lights beaded washboards, closet, wood mantel, pa	s 8 1/2 by 14 sash ?	? To it, 2 20 light 8 by 10		
2		89	The second story is in 2 rooms, a 12 light 8 k story, the back room has 1 window 2 closet,			plain casings headed	washboard 7 ft

Page 7 of 94

Roof 145 Single pitch tin roof and conducts. A ?? flat over about 1/2 the roof ?? and railing to it.

Contributing a	n Historic I	Preservation	Perspective to the Ma	pping the Di	ı Bois Philade	lphia Negro Project		
Policy #	6118	Insurer	Franklin Fire Insura	nce Company	Policy Date	9/9/1845	Property ID	4
Address	425		S. 8th Street				Floorplan	
Owner Name	John Killge	ore & John R I	Hudders					
Notes			g house, Piazza and Back a of Lombard Streets in th			of Eight Street between	Pine and Lombar	d Streets, the third
	window fra	mes front with 1	thers 9" thick. Hemlock jo marble sills, panel shutter nung, marble water table,	s first story and	Venetian revolvi			
Building Type	Resider	nce	Building Ma	terial Bri	ck		Building ID	4
Dimensions	18'x33'	,	# of Floors	3				
Floor	r #	Floor_ID	Building Description					
Cellar		12	A furnace in the front and b	ack cellar for war	ming the house and	l which appear safe. Sash ir	n cellar window and	outside ??
1		13	The first story is one room. light 11 by 20 windows fron doors & windows, neat whit 12 ft high in the clear. A ves	t and 1 13 by 20 vie marble pilaster	window back recess mantel, plank doub	sed to floor and paneled bel le worked passage doors, s	ow, shaped pilasters tucco cornice and c	s with frets to
2		14	The second story is in 2 roc paneled below, plain shape double worked passage do	d pilasters to doo	r windows, plain wh	ite marble pilaster mantel a	nd side closet in ea	ch room, plank
3		15	The third story is in 2 rooms grecian ?? Moulding washb single worked closet door, closets underneath.	oard, neat wood	pilaster mantel each		room, 6/4 double wo	orked passage doors,
Garrett	t	16	The garrett is in 2 rooms, a washboard. Trap door and		pediment top dormo	er window front and back, s	ide closet front roon	n square panel door,
Roof		146	Cedar shingles on roofs, tin Valley back of front building				eaves back. Double	pitch roof 10 ft pitch.

Page 9 of 94

Building Type	Piazza	Building Material Brick	Building ID 29
Dimensions	8'x14'	# of Floors 3	
Floor #	Floor_ID	Building Description	
1	90	Square head door frame with transom & side lights and panel of mahogany newell post first floor, mahogany handrail, heart ste wainscoting under string and closet under stairs first story.	door in the first story. The stairs are continued rail, large turned ps risers, open string, returned nosings, turned ballusters, paneled
2	91	A 12 light 11 by 16 window in second story	
3	92	A 12 light 11 by 14 window in the third story of the Piazza	
Roof	147	Valley back of front building with piazza roof which is single pit	ch
		Cedar shingles on roofs, tin gutters and conductors, wood eave	e and dentils and plain brick eaves back.
Building Type	Residence	Building Material Brick	Building ID 43
Dimensions	13'6"x28'	# of Floors 3	
Dimensions Floor #	13'6"x28' Floor_ID	# of Floors 3 Building Description	
		Building Description The back building has a stairway and pantry off In the first stor windows 3 1/2 in grecian ?? Mouldings and washboard, manted	y which is the kitchen, a plain back doorframe and 3 12 light 11 by 14 el shelf, kitchen range, large dresser with doors and drawers, sink 13 in story, a dumb waiter in the pantry, a flight of winding and tory.
Floor #	Floor_ID	Building Description The back building has a stairway and pantry off In the first stor windows 3 1/2 in grecian ?? Mouldings and washboard, mante and closets underneath, 6/4 double worked passage doors, 8ft square steps to cellar and a flight of winding stairs to second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors at the second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors at the second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors at the second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors at the second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors at the second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors at the second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors at the second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors at the second story is in one room with stairway and pantry off as floor and paneled below.	el shelf, kitchen range, large dresser with doors and drawers, sink 13 in story, a dumb waiter in the pantry, a flight of winding and tory. Is first story 4 12 light 11 by 16 windows 3 of which are recessed to same as second story front. Stucco cornices, neat black and gold d passageway to water closet with revolving blinds and a doorway
Floor # 1	Floor_ID 117	Building Description The back building has a stairway and pantry off In the first stor windows 3 1/2 in grecian ?? Mouldings and washboard, mante and closets underneath, 6/4 double worked passage doors, 8ft square steps to cellar and a flight of winding stairs to second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors a marble pilaster mantel, story 9 ft 6 in hight. A doorway back an	el shelf, kitchen range, large dresser with doors and drawers, sink 13 in story, a dumb waiter in the pantry, a flight of winding and tory. Is first story 4 12 light 11 by 16 windows 3 of which are recessed to same as second story front. Stucco cornices, neat black and gold d passageway to water closet with revolving blinds and a doorway ceiling below plastered.
<i>Floor #</i> 1 2	<i>Floor_ID</i> 117 118	Building Description The back building has a stairway and pantry off In the first stor windows 3 1/2 in grecian ?? Mouldings and washboard, mante and closets underneath, 6/4 double worked passage doors, 8ft square steps to cellar and a flight of winding stairs to second st The second story is in one room with stairway and pantry off as floor and paneled below, pilasters and washboard and doors as marble pilaster mantel, story 9 ft 6 in hight. A doorway back an in it, a veranda portico back with neat diamond ceiling to it and The third story has a bath room partitioned off 4 12 light 11 by	el shelf, kitchen range, large dresser with doors and drawers, sink 13 in story, a dumb waiter in the pantry, a flight of winding and tory. Is first story 4 12 light 11 by 16 windows 3 of which are recessed to same as second story front. Stucco cornices, neat black and gold d passageway to water closet with revolving blinds and a doorway ceiling below plastered.

Page 10 of 94

Contributing a	n Historic P	Preservation I	Perspective to the Mapping the	e Du Bois Philadel	phia Negro Project	
Policy #	4824	Insurer	Mutual Assurance	Policy Date	2/7/1830	Property ID 5
Address	727		Addison			Floorplan
Owner Name	Jame M Wi	ckham				
Notes			s Two story brick building occupie; ront 19 feet 6 inches, including a 3			rth side of Little Pine Street, between
	East a two st	ory brick house	. West a two story frame stable & c	arriage house. Water p	blenty	
	rooms, wash	1	iewing the aboved premises, I find cased & plaister'd, board partitions,	1		as above described. A second story in 2 step ladders planed. All other parts
	Nov 29, 191	1 update: This b	building remains as per survey			
Building Type	Store		Building Material	Brick		Building ID 78
Dimensions	19'6"x22	2'6''	# of Floors 2			
Floor	•#	Floor_ID	Building Description			
1		282	First story in one, not plaisterd, or floor'd	i		
			April 10, 1840 update: The First story re	mains as above describe	ed.	
2		283	Second story in one, not plaister'd, floor	rough sap pine boards g	roov'd	
			April 10, 1840 update: A second story ir brick flue for stove pipe step ladders pla		lows cased & plaister'd, boa	ard partitions, glass 8x10in, a small
Garrett		284	Garrett in one, not plaister'd, floor rough	sap pine boards groov'd	, trap doors, common rough	n step ladders, no chimney in ??

Contributing an	n Historic	Preservation	Perspective to the Mapping	the Du Bois Philadel	phia Negro Project	
Policy #	3596	Insurer	Mutual Assurance	Policy Date	11/5/1814	Property ID 6
Address	710		Addison			Floorplan
Owner Name	Jonathan I	Davis				
Notes	Survey of J feet depth 2		s new two story brick house situat	te at No. 4 on the South sid	de of Little Pine, betwee	en seventh & eighth streets. Front 12
	Common w	vinding stairs fl	oors sap pine bd one of them narr	ow, Board partitions, Glas	s 8 by 10 inches, party	walls 4 1/2 & 9 inches, an ash hole
	West a two Water plen	•	se, East a two story frame Carper	nters Shop. Access in the y	ard by a 2 feet 6 inch a	lley adjoining the Carpenters shop.
Building Type	Reside	nce	Building Material	Brick		Building ID 86
Dimensions	12'x26	,	# of Floors 2			
Floor	#	Floor_ID	Building Description			
1		317	First story 2 rooms plain mantles, w	ashbds, closets & windows ca	ased. Square head front do	por.
2		318	Second story, 2 rooms similar to firs	st story		
Garrett		319	Garrett 1 room & plaister'd trap doo	r, 1 flat top dormer window 12	lights glass 8 by 10 inche	S.

Contributing a	n Historic Pi	reservation	Perspective to the Mapping the	e Du Bois Philadel	phia Negro Project		
Policy #	5791	Insurer	Mutual Assurance	Policy Date	2/7/1844	Property ID	7
Address	726		Addison			Floorplan	
Owner Name	John C Thac	cher					
Notes	Survey of Joh	nn C Thacher's	three story brick house situate on th	e Southeast corner of	Little Pine Street and Pl	easant Avenue.	
	Divided in 2	tennements by	a 4in brick wall				
	Common win	ding stairs in	each, floors narrow white pine board	ls			
	East vacant g	round, South a	three story brick house				
Building Type	Residenc	re	Building Material	Brick		Building ID	77
Dimensions	13'6"x32		# of Floors 3				
Floor	•#	Floor_ID	Building Description				
1		276	First stories each in 1 room, neat mathle	es, washbds. Closets & w	ndows cased. Square head	l front doors, plain j	ambs & architraves
2		277	Second stories, each in 1 room, plain m	antles, washbds, closets	& windows cased		
			A bulk head board partition plaister'd in	the second stories, arour	nd the head of stairs		
3		278	Third stories, each in one room, washbo	ls, closets & windows cas	sed		
Garrett		279	Garrett or loft not floor'd or plaister'd,				
Roof		280	Shed roof, cedar shingled, trap door, tin	spout & conductor			
Cellar		281	Kitchens below plain mantles, dressers,	washbds, closets & wind	lows cased, floors heart pin	e boards, glass 8x1	10in party walls 9

Page 13 of 94

Contributing an	Historic Preservation	on Perspective to the Mapping the Du Bois Philadelphia Negro	Project
Policy #	1598 Insur	er Franklin Fire Insurance Company Policy Date 8/6/1836	Property ID 8
Address	7xx	Addison	Floorplan
Owner Name	Marmaduke L Burr		
		ing house with a one and a half story kitchen, situated on the South side of L ity of Philadelphia. Also a two and a half story brick dwelling house on the rest	
		12 feet 6 inches wide alley on East side build over and 14 feet deep and the K Kitchen, White pine floors in second story and garrett.	Kitchen 12 feet deep. Yellow pine floor in first
Building Type	Residence	Building Material Brick	Building ID 5
Dimensions	12'6"x14'	# of Floors 1.5	
Floor #	# Floor_ID	Building Description	
1	17	First story has a doorway jamb cased in front. Panel door and wood sill and a 12 l wood mantel piece, single worked pannel doors, mouldings and washboard. Story	o
2	18	The second story of the house has 2 12 light 8 by 10 windows and is finished sam clear.	e as first story and story 6 feet 8 in high in the
Garrett	19	The garret of the front house has white pine floor. Double pitch roof 7 feet pitch, C conductors, small 6 light dormer window back, house and kitchen both lathed and in the front house of white pine boards. 2 ft 8 inches going. Common window fram	plastered. 3 flights of plain common winding stairs
Roof	149	Double pitch roof 7 feet pitch, Cypress shingles, wood facia and spouts and tin co	nductors.
Building Type	Kitchen	Building Material Brick	Building ID 30
Dimensions	12'6"x12'	# of Floors 2	
Floor #	# Floor_ID	Building Description	
1	93	One and a half story kitchen. A 6 light sash door in kitchen and window the same, the same height.	mantel shelf, washboard and mouldings, story
2	94	The upper story of the kitchen 4 feet high and 5 feet single pitch roof ceiling to raft Yellow pine floors on upper story.	ers, cedar shingles, a 9 light 8 by 10 window in it.

Page 14 of 94

Roof		150	Cedar shingles					
Building Type	Reside	nce	Building Mater	rial	Brick		Building ID	44
Dimensions	11'6"w	vx13'd	# of Floors	2				
Floor	•#	Floor_ID	Building Description					
1		120	A two and a half story brick dw door and a 12 light 8 by 10 wir pannel doors, sap floor. Story white pine boards.	ndow pani	nel shutters, mouldings	and washboard. Plain wood	matelpiece, side clos	set. Square framed
2		121	The second story has 2 12 ligh in high in the clear.	nt 8 by 10	windows East side and	d is finished as first story, ent	ry around the stairs a	nd story 6 feet 3
3		122	The upper story has 2 light 8 b and ceiling partly on the rafters		lows east side, side clo	oset, mouldings and washboa	ard story 5ft 4in high c	on the east side
Roof		151	Single pitch roof 4 feet 6in pitc posts and rails on roof. commo				ctor, plain brick eave a	and large boards,
Policy #	5347	Insurer	Mutual Assurance		Policy Date	e	Property ID	9
Address	701		Addison				Floorplan	
Owner Name	•							
Notes	Researcher	's note: (702 Pin	e)					
Building Type			Building Mater	rial			Building ID	
Dimensions			# of Floors					
Floor	•#	Floor_ID	Building Description					

Contributing a	n Historic l	Preservation	Perspective to the Mapping th	ne Du Bois Philadel	phia Negro Project				
Policy #	4448	Insurer	Mutual Assurance	Policy Date	4/20/1825	Property ID 10			
Address	705		Lombard Street			Floorplan			
Owner Name	Joseph Huo	ckell							
Notes			kell's three story brick house situate No on the Northwest corner of Seventh & Lombard Streets. Dimensions 13 feet by 38 ed opening in front 8 feet wide by one story high						
	Floors sap pine bds, glass 8x10 inches, party walls 9 inches, ?? Partitions. An ash hole								
	North & We	est, three story	prick houses. Water plenty						
	Noted by #7	07 Lombard's	Phila Contributionship policy #1272	27 as a Hebrew meat ma	arket - Tuesday, June 1	1, 1907			
Building Type	Store		Building Material	Brick		Building ID 80			
Dimensions	13'x38'		# of Floors 3						
Floor	r #	Floor_ID	Building Description						
1		289	The First story in 2 rooms, one occupie flat top pediment, headed pilasters	ed as a grocery & liquor sto	ore, washbds & windows ca	ased, 2 square head front doors, neat			
2		290	Second story, 2 rooms, 1 neat mantle,	surbase, washbds, closets	s & windows cased, stucco	cornices			
3		291	Third story 2 rooms 1 plain mantle, wa	shbds, closet & windows c	ased				
Garrett	t	292	Loft not plaister'd, trap door Common winding stairs						
Roof		293	Shed roof hipt at one corner						
Cellar		294	Kitchen below, plain mantle, washbds,	closets & windows cased					

Contributing a	n Historic I	Preservation I	Perspective to the Mapping the Du Bois Philadelphia Ne	gro Project
Policy #	12727	Insurer	Philadelphia Contributionship Policy Date 6/11/190	07 Property ID 11
Address	707		Lombard Street	Floorplan
Owner Name	e Mary Brad	ley (o) Charles	Pabst (m)	
Notes	705 Lombar	d = Hebrew me	at market. 709 see report	
Building Type	Multi-u	se	Building Material Brick	Building ID 58
Dimensions			# of Floors 2	
Floor	r #	Floor_ID	Building Description	
1		193	Fair construction. Bad repair. Age - 40yrs. Wood cornince, not cut at division stairs. stove heat - unsafe. Gas lighting. Overall Risk is bad. Coal stove - flu	
2		194	dwelling - no descrption	
3		195	dwelling - no descrption	
Roof		196	hipped, tin	

Contributing a	n Historic F	Preservation 1	Perspective to the Mapping the	Du Bois Philadel	phia Negro Project			
Policy #	12727	Insurer	Philadelphia Contributionship	Policy Date	6/11/1907	Property ID 12		
Address	709		Lombard Street			Floorplan		
Owner Name	Mary Brad	ley (o) Charles	Pabst (m)					
Notes	Notes 2 tenants. 707 Lombard = see report. 711 - colored restaurant							
Building Type	Multi-u	se	Building Material	Brick		Building ID 7		
Dimensions			# of Floors 2					
Floor	r #	Floor_ID	Building Description					
1		21	Fair construction. Bad repair. Age - 40yrs. Cased stairs. Heat - stoves - oil, gas - rub Grocery store. Large tank of kerosene oil Oil stove on floor, which is very oily, 1 gal	ber hose - unsafe. Gas in rear surrounded by p	lighting. Overall Risk is bac paper, kindling, wood, etc. I	d. Coal and gas stove - runner hose. Dwelling: ?? With coal stove - no zinc.		
Roof		153	hipped, tin					

Contributing a	n Historic I	Preservation I	Perspective to the Mapping th	he Du Bois Philade	lphia Negro Project				
Policy #	66806	Insurer	Franklin Fire Insurance Com	pany Policy Date	8/12/1887	Property ID	13		
Address	715		Lombard Street			Floorplan			
Owner Name	Rebecca C	Colony							
Notes	Plans includ	le 715 and 717 I	Lombard St.						
	Hemlock joists yellow pine floorboards, reveal window frames front with segment ?? Brick arched heads and marble sills to them, inside shutters, cased window frames back first and second stories and scanthy frames third story, panel shutters to first and second stories, sash double hung except third story back, building plastered, gas pipes introduced.								
Building Type	Multi-u	se	Building Material	Brick		Building ID	8		
Dimensions	16'3"x4	2'	# of Floors 3						
Floor	• #	Floor_ID	Building Description						
1		22	The first story is in 2 rooms entry off th transom and 1 light of sash overhead, sash in them transom 2 lights of sash wood piers ?? frieze and cornice and b doorway with panel door and a step up 6 window back neat wood mantel and flight of square steps and winders at th	marble sill and step, a doo overhead marble sill and s prackets extending across o into the stairway, moulding recess closet, 5/4 single	orway in the store with foldin step and a flat window front the front, a cellar doorway ngs, washboard, 11 ft 9 in s worked passage doors, 3 in	ng sash doors havin having 4 lights 36 by front with wood chee story. The back room	g 4 lights 20 by 30 y 51 sash in it, plain eks and sill; a n has 12 lights 10 by		
2		23	The second story is in 2 rooms entry a Venetian shutters to them, 3 in molding transom with 1 light of sash in it into the mouldings, door and washboard the sa	gs, washboard, neat wood e stairway; the back room	I mantel and recess closet, has a 12 light 10 by 6 wind	side closet, panel do	oors, 10 ft story,		
3		24	The third story is in 2 rooms entry and Inside Venetian shutters to them, 3 in transom sash over entry doorway; the plain wood mantel and 2 side closets,	mouldings, washboard, pla back room has 2 12 light	ain wood mantel, side close s 10 by 12 windows back ?1	ets, square framed pa	anel doors, 8 ft story,		
Garrett	t	25	The garrett is in 2 rooms, stariway betw the stairway, a 12 light 8 by 10 flat top			sircular top rail 18 sa	sh, a closet over		
Roof		154	Double pitch roof, tin roof gutter frame	d on each front brick corni	ice front and brich eave bac	k, tin gutters and co	nductors.		

Page 19 of 94

Building Type	?		Building Material	Brick		Building ID 31		
Dimensions	13'x28		# of Floors 2					
Floo	r #	Floor_ID	Building Description					
1 95		The back building first story is in 2 rooms and stairway and entry a square head door frame with panel door into yard in entry and a flight of square steps and winders to second story and cellar stairs below, the front room has 2 12 light 9 by 15 windows, 3 in mouldings, washboards, a flue for stove pipe, wood mantel shelf and brackets, transom and 1 light of sash over door into entry, square framed ?? 9 feet story, the back room has a plain back door frame with panel door and a 12 light 9 by 15 window in the end and a 12 light 9 by 15 window in the side, closet, mantel shelf, door, mouldings and washboard the same, a flue for stove pipe.						
2		96	The second story is in 2 rooms, stai washboard, closet over the stairway 12 light 9by14 windows, side closet	, wood mantel shelf and brac	kets, square framed panel	doors 8 ft story, the back room has 2		
Policy #	5398	Insurer	Mutual Assurance	Policy Date	6/10/1835	Property ID 14		
Address	715		Lombard Street			Floorplan		
Owner Name	e Laurence I	Lewis & Willia	m Phillips Trustees for					
Notes	See MA po	licy 3166						
Building Type		Building Material			Building ID			
Dimensions			# of Floors					
Floor #		Floor_ID	Building Description					

Contributing	an Histori	c Preservation l	Perspective to the Mapping th	he Du Bois Philadel	<i>phia Negro</i> Proje	ect	
Policy #	5397	Insurer	Mutual Assurance	Policy Date	6/10/1835	Property ID	15
Address	717		Lombard Street			Floorplan	
Owner Nam	e Laurence	e Lewis & Wm Pl	hillips Trustees for MR				
Notes	See MA I						
Building Typ	e		Building Material			Building ID	
Dimensions			# of Floors				
Floo	or #	Floor_ID	Building Description				

Contributing an	n Historic I	Preservation 1	Perspective to the Mapping th	e Du Bois Philadel	phia Negro Project				
Policy #	3234	Insurer	Mutual Assurance	Policy Date	3/31/1812	Property ID 16			
Address	719		Lombard Street			Floorplan			
Owner Name	Nathan Atl	kinson & John	L Stokes						
Notes	Survey of Nathan Atkinson & John L Stokes's new three story brick house Situate No 225 on the north side of Lombard between seventh & eighth streets. Front 16 feet 5 inches Depth 37 feet								
	1 floor heart pine one floor sap pine, other floors narrow sap pine bds. Glass 92 lights 10 by 16 & 78 ditto 10 by 12 inches, party walls 9 inches. Back of the house is a plain open piazza, 3 plain square collumns, brick ash hole. East & west three story brick houses, access back for engines, water plenty								
(Jan 11 1923) Void									
Building Type	Resider	ice	Building Material	Brick		Building ID 90			
Dimensions	16'5"x3	37	# of Floors 3						
Floor #		Floor_ID	Building Description						
1	1 331		First story 2 rooms neat mantles surbase, washbds & windows cased/ marble to the chimnies. Entry half way neat arch reeded pilasters, surbase & washbds, arch head front door neat jambs brick arch						
2	2 332		Second story 2 rooms, similar to first story with closets						
3		333	Third story 2 rooms plain mantles, was	hbds, closets & windows c	cased				
Garrett		334	Farret 2 rooms & plaiste'd, trap door sk head back 12 lights glass 8 by 10 inche board partitions,						
Cellar		335	Kitchen below as customary, floor heart pine bds, common strait stairs,						

.

-

.

-

~

• •

.

- - -

Contributing an	n Historic	Preservation	Perspective to the Mapp	ing the	e Du Bois Philadel	phia Negro Project		
Policy #	5009	Insurer	Pennsylvania Fire		Policy Date	1/26/1846	Property ID	17
Address	727		Lombard Street				Floorplan	
Owner Name	Andrew C	Craig						
Notes	Situated on dwelling.	the North East	corner of Lombard Street and	d Pleasa	nt Avenue (S Perth St)	between Seventh and	Eighth Streets occ	cupied as a store and
Building Type	Multi-u	se	Building Materi	ial	Brick		Building ID	56
Dimensions	17'x38'		# of Floors 3	2				
Floor	•#	Floor_ID	Building Description					
1		186	Store and dwelling. The first sto close and common winders 17 Lombard street has a doorway has a mantel and closet and on	risers an and two	arched head front doorw windows on Lombard Str	ay in the entry on pleasan eet 10 by 18 inch glass wi	t entrance with a far th pannelled shutter	sash. The front on s. The back room
2		187	The second story main house h a mantel and closet to each roo open narrow? Stairs from this s ballusters and is lighted by a wi	om all pla story upwa	inly finished and has an e ard to the garrett having a	entry or lobby 6 feet wide b a half pace to this story an	etween the rooms in d common ?? Hand	n which is a common railing and plain
3		188	The third story is nearly similar back. Common yellow pine sap				s 10 by 12 inch glass	s front 8 by 10 glass
Garrett		189	The garret has two rooms sap f 8 by 10 glass 12 lights. 7 feet si				ed and has 3 windov	ws in the gable end
Roof		190	'A double pitched roof, wood co	ornice froi	nt. Tin hanging spout bac	k. Tin gutters front and tin	spouts all common	throughout.
Building Type	Kitcher	ı	Building Materi	ial	Brick		Building ID	57
Dimensions			# of Floors 1					
Floor	•#	Floor_ID	Building Description					
1		197	The kitchen back communicate plainly finished.	es with the	e back room and has one	window 8 by 10 in glass a	and a common ?? Ai	nd back door all

Page 23 of 94

Contributing a	n Historic P	reservation I	Perspective to the Mapping th	ne Du Bois Philadel	phia Negro Project		
Policy #	14793	Insurer	Philadelphia Contributionshi	Policy Date	2/1/1906	Property ID	18
Address	729		Lombard Street			Floorplan	
Owner Name	e John E. Bai	rd (o)					
Notes	Photo includ	ed					
	Poor condition Substandard	on, substandard construction. P	rth, part of 729-31 Lombard St. Ro construction. Wood cornice not cu Poor repair. Wood cornice. Compos ings on Unity Court. Neighborhood	it, no parapet walls attion paper roof.	-	ance because of co	onstruction, age and
Building Type	Multi-us	ie –	Building Material	Brick		Building ID	10
Dimensions			# of Floors 4				
Floor	r #	Floor_ID	Building Description				
1		30	Bad construction. Bad repair. Age - 50 with non-hazardous store (vacant). 19 stove. 3rd FI - 1 family coal stove. 4th	16 - Cabinetmaker. Shavin	gs. Legs of stove stand on	2 bricks each. 2nd	FI - 1 family coal

Contributing	an Historic	Preservation 1	Perspective to the Mapping the L	Du Bois Philadei	phia Negro Project		
Policy #	14821	Insurer	Philadelphia Contributionship	Policy Date	4/2/1906	Property ID	19
Address	733		Lombard Street			Floorplan	
Owner Name	е						
Notes	photo inclu	ded					
Building Type	e Resider	nce	Building Material B	rick		Building ID 1	1
Dimensions			# of Floors 3				
Floo	or #	Floor_ID	Building Description				
1		31	Fair construction. Bad repair. Age - 70-100 Open stairs. Stoves. Petroleum lamps. Pac need a thorough cleaning, floor in hall bad. attention. 3rd fl - chimney holes should be o	king - straw. Waste a 1st fl vacant dwelling	nd rubbish - neglected. Ov . 2nd fl - plastering cracke	erall risk is bad. Firepla	ace and chimeny
Roof		157	hipped, tin				
Policy #	6271	Insurer	Mutual Assurance	Policy Date		Property ID	20
Address	716 and 71	8	Lombard Street			Floorplan	
Owner Name Notes	е						
Building Type	е		Building Material			Building ID	
Dimensions			# of Floors				
Floo	or #	Floor_ID	Building Description				

.

Page 25 of 94

Contributing a	n Historic I	Preservation 1	Perspective to the Mapping	the Du Bois Philadel	phia Negro Project		
Policy #	1930	Insurer	Pennsylvania Fire	Policy Date	9/3/1831	Property ID	21
Address	7xx		Lombard Street			Floorplan	
Owner Name	Joshua Bro	own					
Notes	North side of	of Lombard betw	ween 7th and 8th. The sixth house	e west from 7th street.			
Building Type	Resider	nce	Building Material	Brick		Building ID 1	2
Dimensions	12'6"x3	32'	# of Floors 2				
Floor	•#	Floor_ID	Building Description				
Cellar		32	The kitchen is in the back cellar hav front.	ing a common floor a deep ?	? And a window, and the w	alls stripped and plast	tered an ash hole
1		33	The first story is of two rooms. The 9 by 12 inches. A mantle to each ro				
2		34	The second story has two rooms and a lobby entry, a white pine floor front and sap floor back. Two windows to each front. The front room has the glass 9 by 11 inches a closet and a mantel to each room.				
Garrett		35	The garret has two rooms and a lob	by entry. Two ?? Dormer win	dows, plastered throughout	t.	
Roof		158	A double pitched roof broken at top.	Cedar shingles to the back a	and top part of the front is o	f cypress. Tin gutters	and spouts
Policy #	2867	Insurer	Mutual Assurance	Policy Date		Property ID	22
Address	7xx		Lombard Street			Floorplan	
Owner Name							
Notes							
Building Type			Building Material			Building ID	
Dimensions			# of Floors				
Floor	•#	Floor_ID	Building Description				

-

Page 26 of 94

Contributing	an Histori	c Preservation F	Perspective to the Mapping the	Du Bois Philadelphia Negro Project		
Policy #	2868	Insurer	Mutual Assurance	Policy Date	Property ID	23
Address	7xx		Lombard Street		Floorplan	
Owner Nam	e					
Notes						
Building Typ	e		Building Material		Building ID	
Dimensions			# of Floors			
Floo	or #	Floor_ID	Building Description			
Policy #	5700	Insurer	Mutual Assurance	Policy Date	Property ID	24
Address	7xx		Lombard Street		Floorplan	
Owner Nam						
Notes						
Building Typ	e		Building Material		Building ID	
Dimensions			# of Floors			
Floo	or#	Floor_ID	Building Description			

-

Contributing a	n Historic P	reservation	Perspective to the Mapping	the Du Bois Philadel	<i>phia Negro</i> Project			
Policy #	3166	Insurer	Mutual Assurance	Policy Date	11/15/1811	Property ID 25		
Address	715 - Rear		Lombard Street			Floorplan		
Owner Name	John C Stoc	ker						
Notes			Westernmost new three story brid es Depth 40 feet	ck house situate No 223 o	on the North side of Lor	nbard between seventh & eighth		
			1 floor heart pine, other floor narr s a plain open Piazza 3 square col			8 ditto 10 by 12 inches, party walls 9 lt.		
	East & west three story brick houses, water plenty. Access back for Engines.							
Building Type	Residenc	ce	Building Material	Brick		Building ID 91		
Dimensions	16'5"x40)'	# of Floors 3					
Floor	#	Floor_ID	Building Description					
1		336	First story 2 rooms meat mantles surbase, washbds & windows cased, stucco cornice marble to the chimnies. Entry halfway wainscoted surbase high, 1 neat arch reeded pilasters, surbase, washbds, stucco cornice, arch head front door, neat jambs, bri arch					
2		337	Second story 2 rooms, neat mantle s	urbase, washbds, closets &	windows cased			
Garrett		338	Garret 2 rooms & plaister'd, trap doo head back 12 lights glass 10 by 12 ir string, board partitions			lass 10 by 12 inches & 1 ditto square nogany rampt handrail stairs, close		
Cellar		339	Kitchen below as customary, floor he	art pine bds, common straig	ht stairs,			

Contributing a	n Historic Preser	vation Perspective to the Map	ping the	Du Bois Philadel	<i>phia Negro</i> Proj	ect	
Policy #	3165	nsurer Mutual Assurance		Policy Date	11/15/1811	Property ID	26
Address	717 - Rear	Lombard Street				Floorplan	
Owner Name	John Clement Sto	ocker					
Notes	Survey of John C S	Stocker's Easternmost new three sto	ry brick ho	ouse Situate No 221 or	n the north side of l	Lombard, between sev	enth & eighth streets.
	inches, party walls	stairs, 2 floors narrow heart pine, 1 : 9 inches. is a plain open piazza, 3 square colo		•		Glass 92 lights 10 by	16 & 68 ditto 10 by 12
Building Type	Residence	Building Mate	rial	Brick		Building ID	92
Dimensions	16'5"x40'	# of Floors	3				
Floor	·# Floo	r_ID Building Description					
1	340	First story 2 rooms, neat mar wainscoted surbase high 1 n					
2	341	Second story 2 rooms, neat r	nantles, sur	base, washbds, closets &	& windows cased.		
3	342	Third story, 2 rooms, plain m	antles, wash	bds, closets & windows	cased		
Garrett	343	Garret 2 rooms & plaister'd tr head back 12 lights glass 8 b board partitions.					
Cellar	344	Kitchen below as customary,	floor heart p	pine bds.			

Contributing a	an Historic	Preservation	Perspective to the <i>Mappin</i>	ig the Du Bois Philadelphia Negro Pro	oject
Policy #	2869	Insurer	Mutual Assurance	Policy Date	Property ID 27
Address	7xx - Rear		Lombard Street		Floorplan
Owner Name	9				
Notes					
Building Type	ę		Building Materia	l	Building ID
Dimensions			# of Floors		
Floo	r #	Floor_ID	Building Description		

Contributing on Historia Progeruption Perspective to the Ma the Dy Rois Philadelphia N Drojaat •

Contributing	an Historic	Preservation	Perspective to the Mapping the Du	ı Bois Philadel	<i>phia Negro</i> Project				
Policy #	3298	Insurer	Mutual Assurance	Policy Date	9/18/1812	Property ID 28			
Address	744		Lombard Street			Floorplan			
Owner Nam	e James C K	enton							
Notes	Researcher	s Note: Noted i	n Historical Society of PA catalog also as	501 8th.					
	744 S & co	r 8 Lombard.							
	Survey of J feet.	ames C Kenton	's new three story brick house situate on t	he South east cor	ner of Lombard & eight	h Streets. Dimensions 19 feet by 30			
	Back buildi	ng 15 feet by 1'	7 feet two stories high.						
	Kitchen 12 feet by 14 feet, two stories high. 1 floor heart pine, other floors narrow white pine boards, glass 60 lights 11 by 17, 60 ditto 10 by 12 & 183 ditto 8 by 10 inches. Party walls 9 inches, an ash hole, materials good & well built.								
	East a three story brick kitchen, Water plenty								
	(Aug 24, 19	911) Inspected A	Aug 24, 1911 Building torn down. Site no	w a modern 4 sto	ry building				
	(Jan 11 192	?) Void							
Building Typ	e Resider	nce	Building Material Brid	ck		Building ID 87			
Dimensions	19'x30	,	# of Floors 3						
Floo	or #	Floor_ID	Building Description						
1		320	First story 1 room, occupied as a grocery stor or plaister'd between joist against the \pounds floor, head doors in the store. In the entry is one flig	Entry at one end no	ot finished, Arch head front				
2		321	Second & third stories & Garrett not finished.	Second floor laid na	arrow sap pine bds				
3		322	Second & third stories & Garrett not finished.						
Garre	tt	323	Second & third stories & Garrett not finished.						
Roof		324	Roof hipt on one corner, no trap door, brick c	ornice					

Contributing an I	instorie i reservation	respective to the mapping the Da Bois I madelphia negro i reject		
Building Type	Residence	Building Material	Building ID	88
Dimensions	15'x17'	# of Floors 2		
Floor #	Floor_ID	Building Description		
1	325	First story 1 room, neat mantle, surbase, washbds & windows cased		
2	326	Second story 1 room, plain mantle, washbds, closets & windows cased. 1 flight common wir	nding stairs	
Garrett	327	Garret 1 room & plaister'd, trap door		
Roof	328	Roof broken pitch, brick cornice		
Building Type	Kitchen	Building Material	Building ID	89
Dimensions	12'x14'	# of Floors 2		
Floor #	Floor_ID	Building Description		
1	329	First story as customary, Chamber, plain mantle, washbds, & windows cased.		
Roof	330	Brick cornice		

Friday, August 25, 2006

Page 32 of 94

Contributing a	an Historic Preservation	Perspective to the Mapping the L	Du Bois Philadel	phia Negro Project				
Policy #	Insurer	Philadelphia Contributionship	Policy Date	9/20/1920	Property ID 29			
Address	710	Lombard Street			Floorplan			
Owner Name	2							
Notes	501-511& 504-512 Lombar RESEARCHER'S NOTE: F Brick. Fair construction, ba	Photo on copy obscures drawings and te d repair. Age - 76. No parapet walls. V sed stairs. Coal cooking stove. No floor	ext for Lombard Ro Vood finish cornice	w properties. View Or , not cut at division wa	iginal at the Historical Society of PA II. Flat roof, slag. Ceiling & partitions -			
	Coal stove. No floor protect	tion. Plaster off section of ceiling.						
	Plaster off nearly all buildings in many places. A number of chimneys have fire boards on each side of ??. Every house has no floor protection under stove. Not fit for perpetual insurance in present condition.							
Building Type	Residence	Building Material B	rick		Building ID 110			
Dimensions	12'x?	# of Floors 3						

Floor #

Floor_ID Building Description

Contributing a	n Historic l	Preservation	Perspective to the Mapping the Du	ı Bois Philadel	lphia Negro Proje	ect	
Policy #	6250	Insurer	Franklin Fire Insurance Company	Policy Date	10/30/1845	Property ID	30
Address	799 (744?)		Lombard Street			Floorplan	
Owner Name	John C Hu	nter					
Notes	Philadelphia frames from hung. Marb	a. 13 & 9 inch y t, marble sills, p le water table a	g house, piazza and back building situate valls, hemlock joist, Carolina pine floor b panel shutters first story & Venetian to see sler steps and platform front, marble sills ain brick eave back, gas pipes introduced	oards, stud partiti cond and third sto to back door fran	ions and buildings al pries, cased frames b	l lathed and plastered ack, panel shutters to	l; Reveal window all and sash double
Building Type	Resider	ice	Building Material Brid	ck		Building ID	59
Dimensions	18'x33'		# of Floors 3				
Floor	•#	Floor_ID	Building Description				
Cellar		201	A furnace in front cellar which appears safe				
1		202	The First story is in one room entry off a vesti brackets under it, a square head doorway fro recess'd to floor and panel'd below and 1 13 worked passage doors, neat white marble m	nt with transom & 1 by 20 ditto to back,	light of glass panel doo pilasters with frets to d	or and 2 12 light 10 1/2 b oors & windows, washb	by 20 windows front oard, plank double
2		203	The Second story is in 2 rooms entry off the b and 1 ditto back, plain white marble pilaster n closet doors, pilasters and washboard, stucce	nantel and side clos	et back room, plank do	uble worked passage do	
3		204	The Third story is in 2 rooms entry and garred grecian ?? Mouldings & washboards, neat we worked closet doors, story 8ft 7in hight; a flight risers to the garrett & closet underneath.	ood pilaster mantel a	& closets each room, 6	4 doub;e worked passa	ge doors single
Garrett	:	205	The Garrett isin 2 rooms, a 12 light 10 by 12	pediment top dorme	er front & back, side clo	set, mouldings & washb	oards, panel doors.
Roof		206	Double pitched roof 10ft pitch. A valley back	with Piazza roof			

Page 34 of 94

Building Type	Piazza	Building Material	Brick	Building ID 60
Dimensions	8'x13'	# of Floors 3		
Floor #	Floor_ID	Building Description		
1	207	A door frame with side lights, transom	& panel door in the first story.	
		The stairs are continued rail, heart step newell post first floor & closet under n	os, mahogany hand rail, turned ballusters, open stri eath, sunk boarding under string:	ng returnd nosings, large turned mahogany
2	208	A 12 light 11 by 16 window in the seco	nd	
3	209	A 12 light 11 by 13 window in the third	story	
Building Type	Residence	Building Material	Brick	Building ID 61
Dimensions	13.6'x28'	# of Floors 3		
Floor #	Floor_ID	Building Description		
1	210	door frame large dresser with doors &	a private stairway & pantry off next the piazza, 3 12 drawers, sink, cooking range, 3 in grecian ?? Moulo rs to second story, and a flight of square steps & wir	lings washboard, 8 ft 3 in story, a dumb
2	211	below, black and gold marble pilaster r	way & pantry off, 3 12 light 11 by 16 windows, 2 of wantel, plain architraves or pilaster to door & window house, plank double worked passage doors.	
3	212	The Third story is in 2 rooms, windows closet, panel doors story 7ft 6in; a wate	the same 11 by 13 glass, grecian ?? Moulding, was er closet in the circular end;	shboard, wood pilaster mantel, side
Roof	213	Single pitch roof about 5 ft pitch		
Building Type	Bath House	Building Material	Frame	Building ID 62
Dimensions	6'x9'	# of Floors 2		
Floor #	Floor_ID	Building Description		

Friday, August 25, 2006

Page 35 of 94

Contributing a		respective to the <i>mapping me</i>	e Du Bois F nituaeipnic	a Negro Flojeci				
1	214		The frame bath house has 2 12 light 10 by 14 windows & Venetian shutters, planed boarding, 8ft 5in story room lathed & plasterd & eiling below, a water closet in it also. (Researcher's Note: it's unclear what's on what floor)					
2	215		The frame bath house has 2 12 light 10 by 14 windows & Venetian shutters, planed boarding, 8ft 5in story room lathed & plasterd & eiling below, a water closet in it also. (Researcher's Note: it's unclear what's on what floor)					
Roof	216	Tin roof						
Policy #	Insure	Philadelphia Contributionship	Policy Date 4/2	20/1928	Property ID 31			
Address	714 - Rear	Lombard Street			Floorplan			
Owner Name	2							
Notes710 & 714 (rear) Lombard St photo included (Researcher's Note: rear is 711 Naudain) RESEARCHER'S NOTE: Photo on copy obscures drawings and text for properties between 710 Lombard & 709 Naudain and 714 Lombard & 711 Naudain. View Original at the Historical Society of PA								
		ood/fair repair. No parapet walls. Wo ased stairs. Coal cooking stove - safe.						
	1 tenant in each - Colored Dwellings & apartments. All in much better repair							
Building Type	Residence	Building Material	Brick		Building ID 111			
Dimensions		# of Floors 3						
Floor	r# Floor_ID	Building Description						

Contributing a	n Historic Preservation F	Perspective to the Mapping the D	u Bois Philadel _l	phia Negro Project	
Policy #	Insurer	Philadelphia Contributionship	Policy Date	4/20/1928	Property ID 32
Address	717	Naudain Street			Floorplan
Owner Name	<u>)</u>				
Notes	717 Naudain St North Side a	about 183' West from S 7th St - photo in	ncluded		
		pair. Brick parapet walls - coped. Wood ed stairs. Coal cooking stove. Gas light			ard roof, slag / tin. Ceiling & partitions - bbish removed properly. Good risk.
	1 family on each floor - Dwo	elling & tenements. Coal stove on each	floor - no floor pro	otection.	
Duilding Ture	Davidance	Duilding Material Du	: .k		Building ID 100
Building Type		Building Material Br	ICK		Building ID 109
Dimensions	18'x28'	# of Floors 2			
Floor	•# Floor_ID	Building Description			
Policy # Address Owner Name	Insurer 719	Philadelphia Contributionship Naudain Street	Policy Date	4/20/1928	Property ID 33 Floorplan
Notes		about 201' West from S 7th St - see 717	for photo.		
	Brick. Good construction/replaster/lath. Joist floors. Goo	pair. Brick parapet walls - coped. Wood od risk.	l finish cornice, cut	t at division wall. Flat re	oof, slag / tin. Ceiling & partitions -
	1 family on each floor - Dwo	elling & tenements			
Building Type	Residence	Building Material Br	ick		Building ID 108
Dimensions	18'x28'	# of Floors 2			
Floor	•# Floor_ID	Building Description			

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project								
Policy #	1316	Insurer	Franklin Fire Insurance Company	Policy Date	7/11/1835	Property ID	34	
Address	7xx		Naudain Street			Floorplan		
Owner Name	Griffith Ev	ans						
Notes 2 buildings insured together. Dimensions are overall dimensions. Plan indicates frame dwelling to the West, Alley to the East. Policy text: "On the north side of Bradford Alley commencing about 90 feet west of 7th Street."								
Building Type	Residen	ice	Building Material Bri	ck		Building ID	13	
Dimensions	21'6"x2	23'6"	# of Floors 2					
Floor	#	Floor_ID	Building Description					
1		36	Sap pine floors, both finished alike, 2 rooms on floor 1st and 2nd story and both stories plastered, a door frame 1st story wood sill and a 12 light 10 by 8 window front and back. Pannel shutters, plain moulding and washboards, plain mantel and side closet back rooms story 7 feet high in the clear,					
2		37	The 2nd stories have a 12 light window front and back finished as 1st stories. Step ladder to garrett					
Garrett		38	Garrett is one room rough floor. 9 light flat to	p dormer window fr	ont of each, cheek shingle	s. ?? Reveal window	r frames front.	
Roof		159	Double pitched roof 8 feet high, cypress shing facia back	gles, tin gutter and c	conductors. Front wood sp	outs back, plain bricl	k eave front wood	

Contributing a	n Historic Pre	eservation l	Perspective to the Mapping the	e Du Bois Philadel	phia Negro Pr	oject	
Policy #	1518	Insurer	Mutual Assurance	Policy Date	4/14/1803	Property ID	35
Address	7xx		Naudain Street			Floorplan	
Owner Name	Pennel Bayle	(Beale?)					
Notes			w two story house situate on the sour boards, surbase, and windows case				
	(Nov 7, 1911)	Inspected No	w 7, 1911. This building has been to	rn down			
	(Jan 11, 1928)	Void					
Building Type	Residence		Building Material			Building ID	97
Dimensions	13'x14'		# of Floors 2				
Floor	•# F	[loor_ID	Building Description				
Policy # Address	1519 7xx	Insurer	Mutual Assurance Naudain Street	Policy Date	4/14/1803	Property ID Floorplan	36
Owner Name	-						
Notes		et deep the ro	w two story house situate on the sou poms have each a mantle, closets, we pine floors.				
	(Nov 7, 1911)	Inspected No	w 7, 1911. This building has been to	rn down			
	(Jan 11, 1928)	Void					
Building Type	Residence		Building Material			Building ID	98
Dimensions	13'x14'		# of Floors 2				
Floor	•# F	[loor_ID	Building Description				

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project									
Policy #	5066	Insurer	Mutual Assurance		Policy Date	12/12/1831	Property ID	37	
Address	705		Rodman Street				Floorplan		
Owner Name	• Thomas Fa	У							
Notes	between Seventh and Eighth Streets, commencing about 48 feet East of 7th Street. Front of the whole 55 feet, including a 3 feet alley, depth 16 feet.								
	East 11 feet	off a three stor	y brick house, West a two	story Fra	ame house.				
Building Type	Residen	nce	Building Mat	erial	Brick		Building ID	14	
Dimensions	13'x16'		# of Floors	3					
Floor	r #	Floor_ID	Building Description						
1		39	First story of each in one room, plain mantels, washboards, closets and windows cased. Arch head front doors, plain jambs, brick arches,						
2		40	Second story each, one roor	n, finishec	d similar to the first story.				
3		41	Third story, each one room, in each. Floors sap pine boa holes, water plenty.					5	

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project									
Policy #	5066	Insurer	Mutual Assurance	Policy Date	12/12/1831	Property ID	38		
Address	707		Rodman Street			Floorplan			
Owner Name	Thomas Fay								
Notes	Notes Survey of Thomas Fay's four new three story brick houses or tenements adjoining, situate No's 705, 707, 709, 711 on the North side of Mary, between Seventh and Eighth Streets, commencing about 48 feet East of 7th Street. Front of the whole 55 feet, including a 3 feet alley, depth 16 feet.								
Building Type	Residence		Building Material	Brick		Building ID	15		
Dimensions	13'x16'		# of Floors 3						
Floor	# Fl	oor_ID	Building Description						
1	42		First story of each in one room, plain mantels, washboards, closets and windows cased. Arch head front doors, plain jambs, brick arches,				plain jambs, brick		
2	43		Second story each, one room, finish	hed similar to the first story.					
3	44		Third story, each one room, plain w in each. Floors sap pine boards, Gl holes. water plenty.						

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project								
Policy #	5066	Insurer	Mutual Assurance	Policy Date	12/12/1831	Property ID	39	
Address	709		Rodman Street			Floorplan		
Owner Name	Thomas Fa	у						
Notes Survey of Thomas Fay's four new three story brick houses or tenements adjoining, situate No's 705, 707, 709, 711 on the North side of Mary, between Seventh and Eighth Streets, commencing about 48 feet East of 7th Street. Front of the whole 55 feet, including a 3 feet alley, depth 16 feet.								
Building Type	Resider	nce	Building Material	Brick		Building ID	16	
Dimensions	13'x16'		# of Floors 3					
Floor	#	Floor_ID	Building Description					
1		45	First story of each in one room, plain mantels, washboards, closets and windows cased. Arch head front doors, plain jambs, brick arches,				plain jambs, brick	
2		46	Second story each, one room, finish	ed similar to the first story.				
3		47	Third story, each one room, plain wa in each. Floors sap pine boards, Gla holes. water plenty.					

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project									
Policy #	5066	Insurer	Mutual Assurance	Policy Date	12/12/1831	Property ID	40		
Address	711		Rodman Street			Floorplan			
Owner Name	Thomas Fa	У							
Notes Survey of Thomas Fay's four new three story brick houses or tenements adjoining, situate No's 705, 707, 709, 711 on the North side of Mary, between Seventh and Eighth Streets, commencing about 48 feet East of 7th Street. Front of the whole 55 feet, including a 3 feet alley, depth 16 feet.									
East 11 feet off a three story brick house, West a two story Frame house.									
Building Type			Building Material			Building ID	17		
Dimensions # of Floors									
Floor	r #	Floor_ID	Building Description						
1		48	First story of each in one room, plain mantel arches,	s, washboards, close	ets and windows cased. Arc	ch head front doors,	plain jambs, brick		
2		49	Second story each, one room, finished simila	ar to the first story.					
3		50	Third story, each one room, plain washboard in each. Floors sap pine boards, Glass 8x10 holes, water plenty.						

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project								
Policy #	4559	Insurer	Mutual Assurance	Policy Date	3/6/1827	Property ID 41		
Address	7xx		Rodman Street			Floorplan		
Owner Name	Owner Name Hugh Catherwood							
Notes	Survey of Hug Depth 29 feet	-	s two story brick house, situate	No. 48 on the North side	e of Mary, between Se	eventh & Eighth Streets. Front 16 feet,		

Common winding stairs, floors narrow white pine bds, glass 10x12 inches, party walls 9 inches, board partitions, an ash hole.

East & West two story frame houses, water plenty

Building Type	Multi-use	Building Material	Brick	Building ID 79
Dimensions	16'x29'	# of Floors 2		
Floor #	Floor_ID	Building Description		
1	285	2 1 1	base, washbds, closets & windows cased. One of th se, washbds & stucco cornice, Arch head front door	
2	286	Second story, 2 rooms, plain mantles,	surbase, washbds, closets & windows cased	
Garrett	287	Garrett 2 rooms & plaister'd, trap doors	5	
Roof	288	Roof broken pitch,		

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project										
Policy #	10996	Insurer	Franklin Fire Insurance Company	Policy Date	11/22/1849	Property ID 42				
Address	714		Rodman Street			Floorplan				
Owner Name	Peter Cullin	n								
Notes	Notes A Three story brick building with a two story brick building in the rear, occupied as a soap and candle manufactury, situate on the South side of St Marys Street, between Seventh and Eighth Streets, beginning about 127 feet West of Seventh Street, in the City of Philadelphia.									
	Dimensions see sketch, 9in outside walls, 4 1/2 in alley walls and partition walls, Reveal window frames ront, wood sills and heads, cased frames back, panel shutters joist and second stories front and second story back, sash double hung, Hemlock joist, rough floor boards in first story and planed and grooved Carolina floorboards in second and third floors.									
The two story building is 18ft wide and 12ft6 deep and is adjoining and connected with the soap house in first and second stories, the back front of the soap house being built on a girder in the third story.										
	The building	g is intended for	three dwellings at some future day.							
	Researcher's	s Note: Sketch s	hows 3 story brick dwelling (13'6"x26'6") beside the stab	les separated by a 2.2	ft alley - uninsured under this policy				
Building Type	Factory	,	Building Material Brid	ck		Building ID 64				
Dimensions	40.6'x2	7.6'	# of Floors 3							
Floor	•#	Floor_ID	Building Description							
1		223	The first story is in 3 divisions, viz soap house, ash house and stable. Brick division walls with openings at the back end, the soap hosue has a large opening front with ledge doors, the ash house has a square head front door frame with panel door transom and a 16 light 9 by 16 wondow front, 2 openings back; the stable has a large opening front with girder across and ledge doors to it, and a girder under the back front, earth floor, a stall enclosed with rough boarding; the story is 8 ft 10 in high in the soap house and ash house.							
2		224	The Second story is in 3 divisions, openings in the partition walls, 2 12 light 10 by 14 windows front and 1 ditto back in the room over the ash house and stable, 8 ft 4 in story, a hatchway in the second and third floors over the stable							
3		225		he Third story is in 3 divisions, 2 12 light 10 by 12 windows front and 1 back in each room, openings in the partition walls, a Irnace and copper kettle in the middle room for melting the tallow and this story used for making candles, 7 ft story						
Roof		226	Double pitch roof about 6 ft pitch, slate roof to conductors, brick eaves front & back; a step is a girder							

Building Type Dimensions	Factory 18'x12'6	Building Material Frame # of Floors 2	Building ID 65		
Floor #	Floor_ID	Building Description			
1	227	The first story has the soap pans in it, part of the back end is of frame and weatherboa	arded.		
2	228	The second story floor is in a line with the front building rough white pine boards, 2 12 light 8 by 10 glass frames west end, a door and 12 lights 10 by 12 window in South end, story 6 ft high on the low side			
Roof	229	single pitch roof about 6 ft pitch, white pine shingle roof (old).			

Policy #	2657	Insurer	Mutual Assurance	Policy Date	2/7/1808	Property ID	43
Address	418		S. 7th Street	9		Floorplan	
Owner Name	Gabriel & J	John Kern					
Notes		abriel & John H nt 13 feet, Deptl	Kern's new two story brick house, site h 15 feet	uate on the west side of	of Seventh, betwe	en Pine & Lombard Stre	eets (Northernmost
	Common wi flat top reed		ass 9 by 11 inches. North gable end	wall 9 inches. Division	n between the adj	oining house of boards p	blaister'd. Frontspiec
	Bounded No	orth & South by	v two story Brick houses, Water not p	blenty			
	(Dec 1, 191	1) Inspected De	ec 1, 1911. Building torn down.				
	(Jan 11, 192	8) Void					
	Researcher's	Note: Interior	pages couldn't be copied, but can be	viewed at the Historic	al Society of PA		
Building Type	Residen	ice	Building Material	Brick		Building ID	101
Dimensions	13'x15'		# of Floors 2				
Floor	•#	Floor_ID	Building Description				
1		360	First story, one room, plain mantle, surb	ase, washboards & wind	ows cased, floor na	rrow yellow pine boards	
2		361	Second story, finished similar to first floo	or, white pine bds			
Garrett		362	Garret plaister'd, floor white pine bds.				
Building Type	Kitchen		Building Material			Building ID	102
Dimensions	12'x9'		# of Floors 1				
Floor	•#	Floor_ID	Building Description				

Contributing	an Histori	c Preservation I	Perspective to the Mapping	the Du Bois Philadelphia Negro Project		
Policy #	2656	Insurer	Mutual Assurance	Policy Date	Property ID 44	
Address	420		S. 7th Street			
Owner Nan	ne					
Notes						
Building Ty	pe		Building Material		Building ID	
Dimensions			# of Floors			
Flo	or #	Floor_ID	Building Description			

Contributing a	n Historic Pr	eservation P	Perspective to the Mapping the	Du Bois Philadel	Iphia Negro Project		
Policy #	2655	Insurer	Mutual Assurance	Policy Date	2/7/1808	Property ID	45
Address	422		S. 7th Street			Floorplan	
Owner Name	e Gabriel & Jo	hn Kern					
Notes		oriel & John Ko 13 feet, Depth	ern's new two story brick house, situa 15 feet	te on the west side o	of Seventh, between Pin	e & Lombard Str	eets (Southernmost
Common winding stairs, glass 9 by 11 inches. South gable end wall 9 inches. Division between the adjoining house of boards plaister'd. Frontspiece flat top reeded pilasters							
	Bounded Nort	th & South by	two story Brick houses, Water not ple	enty			
Building Type	Residence	е	Building Material B	Brick		Building ID	99
Dimensions	13'x15'		# of Floors 2				
Floor	r#	Floor_ID	Building Description				
1	:	356	First story, one room, plain mantle, surbas	e, washboards & wind	ows cased, floor narrow ye	llow pine boards	
2	3	357	Second story, finished similar to first floor,	white pine bds			
Garret	t S	358	Garret plaister'd, floor white pine bds.				
Building Type	Kitchen		Building Material			Building ID	100
Dimensions	13'x10'6'	,	# of Floors 1				
Floor	r# 1	Floor_ID	Building Description				
1	:	359	Kitchen 13 feet by 10 feet 6 inches one sto	ory high finished as usu	ual. Ashes kept in cashs		

Contributing a	n Historic	Preservation 1	Perspective to the Mapping th	e Du Bois Philadel	phia Negro Project					
Policy #	4837	Insurer	Mutual Assurance	Policy Date	1/7/1814	Property ID 46				
Address	424		S. 7th Street			Floorplan				
Owner Name	Josiah Eva	ns								
Notes	Researcher'	s Note: Assume	d #424 S 7th. Policy only lists 1814	address as #224						
	Survey of Joinches, deput		w two story brick house situate No.	224 on the West side of	of Seventh, between Pir	ne & Lombard Streets. Front 13 feet 6				
			ard partitions, 2 floors, narrow sap valls 4 1/2 inches, an ash hole.	pine, other floors narro	w white pine bds. Glass	s 12 lights 10 by 12, 24 ditto 9 by 11 & 36				
	North a two story & south a three story brick houses									
	Access in the yard by a 2 feet 6 inch alley from Little Pine Street									
	(Apr 13 183	30) policy owned	d by Isaac Sullivan							
	(Dec 1 191)	l) This building	remains as per survey							
Building Type	Resider	nce	Building Material	Brick		Building ID 85				
Dimensions	13'6"x2	26'	# of Floors 2							
Floor	#	Floor_ID	Building Description							
1		313	First story 2 rooms, plain mantles, surb pilasters	ase, washbds & windows	cased. Square head front o	door, plain flat top pediment, reeded				
2		314	Second story, 2 rooms plain mantles, s	urbase washbds, closets &	& windows cased,					
Garrett		315	Garret 2 rooms & plaister'd, trap door, b	pattlements						
			2 common square head dormer window	vs 12 lights each, glass 9 l	by 11 inches					
Roof		316	Roof broken pitch,							

Contributing a	n Historic Pre	servation I	Perspective to the Mapp	ing the Du l	Bois Philade	lphia Negro Pro	oject
Policy #	3951	Insurer	Mutual Assurance		Policy Date	3/30/1819	Property ID 47
Address	426		S. 7th Street				Floorplan
Owner Name	Magnus Crosb	y					
Notes	Survey of Magi inches, Depth 2		three story brick house situa	ate No 226 on	he west side of	f Seventh between	Pine & Lombard Streets. Front 13 feet 6
			her floor white pine bds, glas th a two story & South a thre				o 8 by 10 inches, party walls 9 inches, boar back. Water plenty
	(Dec 1, 1911) 7	This building	remains as per survey				
	(June 21, 1918) brick house.	On viewing	the herein described buildin	ng situate on th	e west side of ²	7th the south house	e above Lombard #426 S 7th. A three story
	Wood toilet in	yard with iro	on hopper, gal(?) tank, etc.				
Occupied as a dwelling (colored)							
	(Jan 11, 1928)	Void					
Building Type	Residence		Building Mater	ial Brick			Building ID 84
Dimensions	13'6'x26'		# of Floors 3				
Floor	•# F	loor_ID	Building Description				
1	30)7	First story, 2 rooms, plain mant door, plain flat top pediment, re		shbds, closets &	windows cased, Enti	ry, surbase & washbds, Swuare head front
							platform & sill, square head reeded front door t sash outside shutters, 6" marble belt course
2	30)8	Second story 2 rooms similar to	o the first story			
			(June 21, 1918) Second story fi	ront - two windov	vs plank front fra	mes wood sills 12 lt s	sash
3	30)9	Third story, 2 rooms 1 plain ma	nle, washbds, cl	osets & windows	cased	
			(June 21, 1918) Third story two	windows same	as above. Flat wo	ood cornice.	

Contributing an Historic	Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project								
Garrett 310		Loft floord, rough bds, trap door							
		Common winding stairs							
Roof	311	Roof a fourth worn, battlements, brick cornices							
	(June 21, 1918) Flat wood cornice. Tin roof & gal(?) conductors, underdrained								
Cellar	312	Kitchen below, closet & washbds							
		In kitchen, one iron sink, cold water only							
Policy # 4448	Insurer	Mutual Assurance	Policy Date	Property ID 49					
Address 432		S. 7th Street		Floorplan					
Owner Name Notes									
Building Type		Building Material		Building ID					
Dimensions		# of Floors							
Floor #	Floor_ID	Building Description							

Contributing a	n Historic	Preservation	Perspective to the Mapping the L	Du Bois Philadel	<i>phia Negro</i> Proje	ect				
Policy #	14179	Insurer	Philadelphia Contributionship	Policy Date	12/16/1931	Property ID 50				
Address	512		S. 7th Street			Floorplan				
Owner Name	e Sebastian	Benedetto								
Notes	512 South	7th St Phila. PA	. Liberty of a grocery store in 1st story.	- photos included.						
	Ceilings /	walls - plaster / l	fair construction & repair. Age - about ath. Joist floors. Cased stairs. Heating - ding - secure. Ashes kept outside. Wast	gas, hot water. Oil	stove - iron pipe, sa	fe. Cooking stove - gas, safe. Lighting -				
	2 tenants. I	Restaurant & dw	ellings							
	(2/9/1944) 512 South 7th St Being the SW corner of Naudain St, Phila PA (photo incl) Pri? Is granted for a carpenters shop with not more than one hand in 1st story, remainder of building to be occupied for dwelling purposes only by not more than two families.									
	Age - prob. 60yrs. Good repair. Metal cut cornice. Slag roof. Joist floors. Lath & plaster ceilings / partitions. Cased stairs. Gas cooking stove. Hot water heat. Coal hot water. Electric lighting. Ashes - metal.									
	Electric wi	ring in basemen	t should be examined by a competent el	ectrician and correc	t the wires which ha	ang on pipes - nails, etc.				
	Waste & R	ubbish OK. Goo	od risk.							
		nd declining can ancel if more tha	cellation. n 4 families. Subject to wiring being co	prrected.						
Building Type	Multi-	use	Building Material B	rick		Building ID 113				
Dimensions	18'x28		# of Floors 3							
Floor	r #	Floor_ID	Building Description							
Cellar		379	Hot water heater - gas tank heater							
1		380	Front room - carpenter shop. 1 work bench stove - alcohol lamp & candle.	1 handi - clean bed b	ehind screen. Tenant e	evidently sleeps & works in this room. Oil				

Building Type Dimensions	Residence 14'x39'	Building Material # of Floors 3	Building Material Brick # of Floors 3			
Floor #	Floor_ID	Building Description				
1	381	1st floor - Rear dwelling - gas range.				
2	382	2nd floor - Rear dwelling - gas range.	3rd floor - vacant			
3	383	3rd floor - vacant				
3	065 Insurer 16	Mutual Assurance S. 7th Street	Policy Date	Property ID 51 Floorplan		
Building Type Dimensions		Building Material # of Floors		Building ID		
Floor #	Floor_ID	Building Description				

Friday, August 25, 2006

Page 54 of 94

Contributing a	n Historic l	Preservation	Perspective to the Mapping	the Du	Bois Philadel	phia Negro Pr	oject	
Policy #	63438	Insurer	Franklin Fire Insurance Co	mpany	Policy Date	10/27/1884	Property ID	52
Address	518		S. 7th Street				Floorplan	
Owner Name	Lincoln Blo	lg & Loan Ass	oc of Philadelphia					
Notes			and dwelling house situate on the ty of Philadelphia	West sid	de of Southe Sev	enth Street No 51	8 North West corner of	f St Marys Steet in
	outside pane	el shutters to fir	5ft 6 in deep Hemlock joist yello st and second Venetian to third st litto in third story, building plaste	ory, case	ed window frame	es back outside pa	nel shutters to first stor	y, sash double hung
Building Type	Tavern		Building Material	Bric	·k		Building ID	71
Dimensions	18'x35'	6	# of Floors 3					
Floor	•#	Floor_ID	Building Description					
1		249	The First story is in two rooms the free transom and folding sash doors with each front 3in mouldings 5/4 panel p. The back room is the kitchen has a dight 10x 15 window, and a 12 light 9 shelf a gas oven a flight of stairs to stransom and panel door Story 9 ft	16 lights bassage de circular he bx11 ditto l	of 8 by 12 sash in e oors walls wainsco ad door grame on back 3 1/2 in mould	each pair, lifting shu ted 4 ft 6in high with the side with a three dings washboards, 5	tters to them and a 20 ligh a planed and grooved boar e light transom sash and a 5/4 panel doors a closet a v	t 10x15 window in ds, story 10ft. panel door and a 16 vood bracket mantel
2		250	The Second story is in two rooms en of front room 3 1/2 in mouldings was The back room has a 12 ligh 10x14 doors and an open fireplace, a door third story with close string turned ne	hboards 5 window m frame in t	5/4 panel doors a c ouldings washboar he back of entry wi	loset a wood pilaste ds the same, a clos th transom and old l	r frieze mantel, stucco corr et a wood mantel shelf 4/4 ledge door a flight of rail ar	nice on the ceiling. square framed
3		251	The Third story is in two rooms entry room 2 in mouldings washboards 5/4 12 light 10x14 window mouldings, washelf, Story 7ft9in a 12 light 9x11 wir	4 panel do ashboards	oors a closet an ope s, passage door sa	en fireplace and woo me a closet with a le	od pilaster fireze mantel. T edge door, an open fireplac	he back room has a
Garrett		252	The Garrett is in two rooms stairway end sash not hung 2in mouldings wa			•	5	windows in gable
Roof		253	A shingle roof pitching to front and b boards and has a rough board roof	ack tim co	onductors nd brick (eave front. A rough s	shed back 9ft deep enclos	ed with rough

Contributing a	an Historic Pro	eservation P	erspective to the Ma	pping the Du Bois .	Philade	<i>lphia Negro</i> Pi	roject			
Policy #	1517	Insurer	Mutual Assurance	Polic	y Date	4/14/1803	Property ID 53			
Address	510 (?)		S. 7th Street				Floorplan			
Owner Name	Pennel Bayle	(Beale?)								
Notes	Notes Survey of Pennel Bayles, new three story house situate on the west side of Seventh Street between Cedar and Lombard Streets, and on the corner of Bradfords Alley (Loulin? Street). Dimensions 18 feet front and 35 feet deep.									
	The rooms have each a mantle, closets, washboards, surbase, and windows cased, garrets plastered and trap door, open newell stairs with a mahogany rampt handrail, and swuare ballusters, kitchen below, lower floors yellow inch pine the others white pine, large glass, pediment and pilasters in front two trees									
	(Dec 1, 1911) Inspected. Building torn down									
	(Jan 11, 1928)	Void								
Building Type	e Residence	2	Building Ma	terial			Building ID 96			
Dimensions	18'x35'		# of Floors	3						

Floor # Floor_ID Building Description

Contributing a	n Historic I	Preservation	Perspective to the Mapping	the Du Bois Philade	lphia Negro Project		
Policy #	3265	Insurer	Pennsylvania Fire	Policy Date	9/11/1835	Property ID	54
Address	5xx		S. 7th Street			Floorplan	
Owner Name	Benezet Ph	ilanthropic So	ciety House				
Notes	Dimensions	about 15 feet b	y 42 feed including an octagonal	end of 5 feet on the back	k end		
Building Type	Resider	псе	Building Material	Brick		Building ID	63
Dimensions	15'x42		# of Floors 3				
Floor	•#	Floor_ID	Building Description				
1		217	The First story has one room and a leading to the garrett in the lobby. To shutters, a wood matnle subbase an	wo windows ront the class 1	1 by 16 inches two windows	s back 10 by 16 inch	
2		218	The Second story has one room hea front 11 by 16 inch glass with Veneti finished throughout				
3		219	The Third story is divided by plaster sap pine floor two windows front 6 lig	• •	2		
Garrett		220	The Garrett has two rooms white pir	ne floor			
Roof		221	A double pitched roof cedar shingles	s. Tin gutters Wood cornice.			
Cellar		222	The Cellar is floored and has a sash	door and a common windin	g stairway		

Contributing a	n Historic	Preservation	Perspective to the Mapping	the Du Bois Philadel	phia Negro Project		
Policy #	2336	Insurer	Pennsylvania Fire	Policy Date	10/3/1832	Property ID	55
Address	5xx		S. 7th Street			Floorplan	
Owner Name Mathew Scanlan							
Notes	Survey of Mathew Scanlan two three story brick hosues occupied as a dwelling houses and stores situated on the East side of Seventh Street about 20 feet South from Lombard.						
Dimensions about 30 feet front including both houses and an alley between them which is build over by 28 feet deep.							
Both houses are of similar kind and join each other.							
Building Type Multi-use		ise	Building Material	Brick		Building ID	66
Dimensions	30'x28'	1	# of Floors 3				
Floor # Fl		Floor_ID	Building Description				
1		230	The First story ahs two rooms. The f doors, the back room has a twin win trimmings to the windows and doors	dow the glass 10 by 15 inch	glass pannelld shutters thr	oughout a wood ma	
2		231	The Second story has two rooms and a lobby entry two windows front the glass 10 by 15 inches Venetian shutters a mantle and closet to each room a twing window back 10 by 15 inch glass sap floor				
3		232	The Third story has two rooms and a lobby entry. Sap floors and is nearly similar to the second story, the window 10 by 12 inch				
Garrett		233	The Garrett has one room sap floor				
Roof		234	A double pitched roof cedar shingles a segment head dormer window, tin gutters and spouts the back being hanging spouts & brick eaves				
Cellar		235	The Kitchen is in the cellar having he	eart floor and a twin window ?	16 lights 8 by 10 glass a cl	oset under the stairs	s and a ?? Closet

Contributing a	n Historic Pi	reservation P	erspective to the Mappin	g the Du Bois Philadel	<i>lphia Negro</i> Pro	vject
Policy #	4921	Insurer	Pennsylvania Fire	Policy Date	8/8/1845	Property ID 57
Address	403		S. 8th Street			Floorplan
Owner Name	John Neill					
Notes	Survey of John Neill Three story brick dwelling house having a 2 story back building and a frame wash house and bath house situated on the South side of G?? Street about 162 feet 6 inches West from Thirteenth Street in Spring Garden					
	Researcher's	Note: ??? Rema	ining data not transcribed. Bu	ilding not on 8th street as e	expected	
Building Type			Building Material	!		Building ID
Dimensions			# of Floors			

Floor #

Floor_ID

Building Description

Contributing a	n Historic P	reservation	Perspective to the Mappin	g the Du Bois Philadel	phia Negro Project		
Policy #	7147	Insurer	Pennsylvania Fire	Policy Date	10/28/1861	Property ID	59
Address	407		S. 8th Street			Floorplan	
Owner Name	H Crittende	n					
Notes	Floorplan inc	cluded					
Building Type	Residence	ce	Building Material	Brick		Building ID	18
Dimensions	19'x34'		# of Floors 3				
Floor	•#	Floor_ID	Building Description				
1		51	The first story (12 feet high) has o sash with marble lintel and vestibu skirting throughout is 8 1/2 inches 1/2 inches wide to doors in a white 20 inch lights. One window back under the windows, the front entra stairsstucco cornice and center pion	ule at the front door with a pann wide, moulded. 2 entry doors 4 e Italian marble mantel and hea 12 by 20 glass pannelled shutte ance doors are 2 inch plank 4 pa	elled door and ?? Side ligh pannelled of 2 inch plank rth worth 60 dollars, 2 wind rs. Reveal frames front, bu annelled. Carolina pine floo	ts and transom hea and plated back furr lows front with plate It no mantle lintel he rs good quality thro	d sash over it. The niture, architraves 6 glass 11 inches by eads dado pannells ughout the house,
2		52	The second story 10 feeet 6 high I room and a door between rooms. each room and a breast closet in e back, glass same as front with par cornice in the ceiling.	All have pilaster architraves 5 in each, 2 windows front the glass	nches wide. Skirting 8 1/2 i 12 by 20 inches all Venetia	nches wide a marble an rolling blind shutt	e plain Italian, in ters, one window
3		53	The third story 8 feet 5 high has 2 room. A common straight stairway under it ?? 14 risers in the stairs. Y Venetian blind shutters one windo inches thick with moulding on it gr partition a path room in the back b	r against the S wall having plain Yellow pine steps throughout th w back the same. A wood man recian moulding trimmings to do	mahogany handrailing and e house, the room 2 windo tel and closet each room ar ors and windows, a door to	d ballusters 2 feet 9 ws front the glass 1 nd 4 pannelled door each room and on	wide going a closet 2 by 14 inches. 6/4 thick. Skirting 7
Garrett	t	54	The attic has 2 rooms, common C front with ridge pediment heads 12 ceiling the room plastered and a tr	2 lights 10 by 12 inch glass all p	lainly finished and pastere	d. The collar beam i	is 8 feet high to the
Roof		160	The roof about 1/3 of the span dou the cornice. Common rafters and o		n cedar shingles and has tir	n gutters. The front	gutter is formed in

Page 60 of 94

Building Type Piazza **Building Material Brick Building ID** 33 # of Floors 3 **Dimensions** 8'x14' Floor # Floor ID **Building Description** 1 98 The Piazza contains a side doorway with side lights and square head and a stairway ?? Continuous geometrical mahogany handrailing with a newell the same at bottom and turned ballusters. The first story flight 21 risers 3 feet wide going has a half pane into a door from it into the back landing. 2 99 19 risers in the 2nd flight landing on the 3rd floor bath lighted with a window on each landing. There is a private winding stairway back of the main stairs in a lobby 6 feet by 4 deep divided with a partition from the main stairs has 13 risers extends from the cellar to the 3rd story back building. A large pantry closet in the ciruclar end opposite the private stairs a closet in each story ??. A dumb waiter closet in the lobby of private stairs 1st and 2nd storys in the pantry closets, circular ends. 3 100 The bath room is in the 3rd story nearby on a level with the 1/2 ?? Of the main stairs between the 2nd and 3rd story. Hot and cold water included. **Building** Type Residence **Building Material Building ID** 45 Brick 13'x27' # of Floors 3 **Dimensions** Floor # Floor ID **Building Description** 1 123 The first story is the kitchen. Has 2 windows 11 by 14 inch glass a pantry a large closet in the circular overlap which contains the dumb waiter closets is shelved and has cup hooks enclosed with 6 doors and 3 drawers. Common skirting and 6 inch plain trimmmings pannelled shutters. A door into the work house which is a frame projecting about 10 feet is 2 storys in height the 1st story has the brick pavement from a door and is enclosed with common weather boarding. 2 124 Second story back building 9 feet 5 high, has a dining room with 3 windows 11 by 16 inch glass with pannelled shutters a marble mantel and hearth pilaster architraves. The doors 6/4 thick pannelled Carolina pine floors. There is a conservatory room communicating with the dining room is of frame. Encloses an irregular space about 10 by 13 feet including the brick provy which is a water closet communicating by a passageway with the dining room SouthEast corner also a bath room about 4 by 6 in the same corner ?? Eastward having furniture as usual and hot and cold water introduced. The conservatory room communicates with the dining room by a folding sash doorway 3 feet 4 by 8 feet. There is a ?? ?? On the north side of the apartment. 1 window and 2 doors eastward 8 lights each one in the East end. 1 window 12 by 17 inch glass. The frame conservatory has a tin covered room and encloses a space about 10 by 13 feet is at the East end back building.

Contributing an	n Historic l	Preservation I	Perspective to the Mapping the	e Du Bois Philadel	phia Negro Project		
Policy #	7300	Insurer	Mutual Assurance	Policy Date	7/15/1867	Property ID	60
Address	419		S. 8th Street			Floorplan	
Owner Name	Samuel M	Anderson					
Notes	•	amuel M. Ander ne & Lombard st	rson's Three story brick house, Piazz treets.	a & Three story back	building, situate No 403	3 on the East side	of Eighth street,
	Dimensions feet	, Main house, F	ront 19 feet Depth 33 feet. Piazza 8	feet by 13 feet. Back b	ouilding 14 feet by 27 fe	et 6 inches. Vera	ndah 10 feet 4 in by 14
	(Nov 30, 19	11) Inspected					
	(July 17, 19	35) Policy cance	elled July 17th 1935.				
			South 8th St - number eventually cha o fragile to risk copying interior pag				
Building Type	Resider	ice	Building Material	Brick		Building ID	93
Dimensions	19'x33'		# of Floors 3				
Floor	#	Floor_ID	Building Description				
1		345	First story in one room & entry subed & pilasters. Stucco cornice & center with b front door. One light transom over & rad plain entabliture at end of Entry, with 2 walls papered	and on ceiling. White Itali iating blind inside. Square	ian marble mantel, folding o e head vestibule frame 3 lig	doors from entry to transom & side I	room, square head ights close panel door,
2		346	Second story in 2 rooms & entry to front kneed pilasters, stucco cornice, 2 marble sutters, walls papered				
3		347	Third story in 2 rooms & entry to front ro closets, in entry a flight of stairs to garre Venetian & panel shutters				
Garrett		348	Garrettin 2 rooms, moulded base, yellov door & ladder,	v pine floor & mouldings, :	2 closets, 2 square haed d	ormer windows 12 l	ights 10 by 12 trap
Roof		349	Wood cornices front, brick back, shingle	roof, tin gutters & conduc	ctors		

Building Type **Building Material Building ID** 94 Piazza **Brick** # of Floors 3 **Dimensions** 8'x13' Floor_ID **Building Description** Floor # 350 1 Piazza contains 2 flights continued mahogany rail stairs to 3rd story with newell & turned ballusters painted, closet under, Venetian frame with side lights & transom, one 12 light window 12x16 & one ditto 12x14 panel sutters, cornice and roof as house, walls papered **Building Type** Kitchen **Building Material Brick Building ID** 95 **Dimensions** 14'27' # of Floors 3 **Building Description** Floor # Floor ID 1 351 Back building First story inone room, as kitchen, moulded base, windows cased, yellow pine floor & mouldings, large dresser, range & iron sink, large pantry in circular corner, ?? Shelved one side & closets the other, Copper wash sink dumb waiter to 2nd story, a flight of stairs to 2nd story, one inder to cellar, three 12 light windows 11x14 shuttered 2 352 Second story in one room, subed & moulded base, windows cased, panel under, yellow pine floors & 5 inch flat & kneed pilasters, stucco cornice & center, Black & Gold marble mantel, large pantry in circular corner with shelves & closets, four 12 light windows 11x16 panel shutters, walls papered In rear of this story is a frame verandah Yellow pine floor painted & plastered ceiling, fancy wood cornices, tin roof, supported one side by 2 open pilasters & fancy wood work under cornice, rail between pilasters,, Venetian blinds on east and part of west side, brick water closet in part of verandah, 4 light window in ditto 10x14 Venetian blinds 3 353 Third story in one room, moulded base, windows cased, yellow pine floor & moulding one closet, wood mantel, bath room, tub lined with zinc, four 12 light windows 11x13 panel shutters, brick floor & sash & ?? Work in the windows, gas throughout Roof 354 roof & cornice as house 355 Cellar heater in cellar

Contributing a	an Historic Preservation	Perspective to the Mapping the D	u Bois Philadel	phia Negro Project		
Policy #	6654 Insurer	Mutual Assurance	Policy Date	5/15/1858	Property ID	62
Address	425	S. 8th Street			Floorplan	
Owner Name	e George W Bernadore					
Notes	Survey of George B Bernac side of Eighth St South of H	lore's three story brick house, with three Pine Street.	story brick Piazza	and three story brick ba	ick building. Situa	ate No. 409 on the East
	Researcher's Note: Owners	hip chanages to Eliza Baxter & Jennie R	lowe at some time	(shortly?) after address of	changes to No 42	5 S 8th Street
	(Sept 16 1907) Don't see an present.	ny alterations. Occupied for the sale of D	Dental materials an	d dwelling. No manufact	tury at present. No	o advance in rate at
	(Sept 20 1907 for C Jones)	No. 425 South 8th Street, Philadelphia	and occupied as a o	dwelling and for exhibiti	on of machinery,	using electric current.
	a.m. glass put in, electric lig	ng alterations have been made. The top p ghts have been put in on the first floor, a with ventilating pipe etc. The building is	slo electric power	for grinding teeth etc on	the third floor, a	
	(Oct 31, 1910) No. 425 Sou not more hazardous	th 8th Street, Philadelphia, and occupie	d for Dental work,	and show room, and for	dwelling purpose	es, or for other purposes
	(Nov 21 1911) This buildin	g remains as per survey				

Researcher's Note: Policy void Sept 10 1930

Building Type	Residence	Building Material	Brick	Building ID 81
Dimensions	18'x33'	# of Floors 3		
Floor #	Floor_ID	Building Description		
1	295	panel shutters, front door in two panels	s sunk jambs & square transom, vestibule do 9 in pilasters, subbed & moulded base, stuc	ghts 11x20 & one ditto 13x20, panels under it & or frame with side lights one Italian marble co cornice & centres, across the entry back is a
2	297		els under two closets, two marble mantels, o	nts 12x20 with Venetian blind shutters & one doors & windows trimmed with 5 1/2 in

3 298 Third story in two rooms & entry off back two windows 12 lights 12x14 with blind shutters & one ditto same size, panel shutters, two wood mantels, two closets, doors & windows trimmed with 3 1/2 in moulding subbed & moulded base straight stairs to garret, poplar newell, mahogany rail square pine balusters, yellow pine steps, closet underneath, yellow pine floor 299 Garret in two rooms, one segment & one ridge dormer each 12 lights 10x12, one closet, doors trimmed with 2 1/2 moulding plain Garrett base, step ladder to loft, trap door Roof 300 double pitched roof cedar shingles tin gutters, wood cornice front, brick eave, tin conductors **Building Type Building ID** 82 Piazza **Building Material** Brick **Dimensions** 8'6"x8' # of Floors 3 Floor # Floor ID **Building Description** 1 296 Piazza, a Venetian side door with side lights & transom & inside shutters, a continued rail stairs to 3rd story mahogany newell & rail, turned maple balusters, panel wainscott, with closet underneath, 5/4 yellow pine steps, one window 12 lights 11x16 & one ditto 11x14 with panel shutters Roof 302 roof cedar shingles & brick eave **Building Type** Residence **Building Material Brick Building ID** 83 13'6"x33' **Dimensions** # of Floors 3 Floor # Floor ID **Building Description** 1 301 First story back in one room & entry to stairs, fan windows 12 lights 11x14 panels under & panel shutters, large closet in circular corner, with shelves & a dumb waiter to 2nd story, doors & windows trimmed with 3 1/2 moulding subbed & moulded base, cooking range & boiler, iron sink with hot & cold water, large dresser with 8 doors & 4 drawers, floor yellow pine, winding stairs to 2nd story 2 303 Second story back in one room & entry to stairs. Four windows 12 lights 11x16 panels under & panel shutters large closet in circle shelved, with 4 doors & 3 drawers a zinc(?) sink with hot & cold water, doors & windows trimmed with 5 1/2 in pilasters, subbed & moulded base one black Italian marble mantel, stucco cornince & centre, floor yellow pine. Back of this story is a verandah 10ft 9 in by 8 ft 10 in exclusive of an entry on the north 4 ft wide leading to a brick privy back. In the entry a door & 1 opening filled with olote(?) blinds. Verandah floor yellow pine gullied Roof with a hip on corner, covered with tin, subbed with open worked posts, with diamond railing between, ceiling plastered drop facia on one side & back

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro Project

Page 65 of 94

3	304	Third story back in one room & entry & bath room, four windows 12 lights 11x13 panel shutters, closet & wood mantel, doors & windows trimmed with 3 1/2 mouldings moulded base, wood bath tub, lined with galvanised copper, hot & cold water.
		Sash double hung throughout, gas pipes concealed, rooms papered to garret, except the kitchen which is painted
Roof	305	Single pitched roof cedar shingles, tin gutter & brick eave
Cellar	306	Cellars brick paved, a furnace front & back, with flues & registerd to 3rd story, sash and ?? Frames to cellar windows, marble ashlars front to 1st floor

Contributing an Historic Preservation Perspective to the Mapping the Du Bois Philadelphia Negro ProjectPolicy #22264InsurerPhiladelphia ContributionshipPolicy Date2/17/1922Property ID63

		-	-	
Address	427	S. 8th Street		Floorplan

Owner Name Louis J. Gandolfo

Notes #427 South 8th St. East side about 18' north of Lombard St. Phila. PA - ?? Of apartments throughout.

Brick construction. Fair construction & repair. No parapet walls. Wood finish cornice - not cut at division wall. Hipped, tin roof. Ceilings & partitions - plaster / lath. Joist floors. 2 stairs - open & cased. Lighting - Gas, safe. Ashes kept outside. Waste / rubbish removed properly. Risk - Fair.

2 brick furnaces - 1 not in use. Gas range. 1st Floor - dwelling 2nd Floor - 1 old lady has 2 front rooms. Gas stove. No access. Template has several rooms for rent.

2 tenants at present. Furnished rooms & dwellings - #429 S 8th - see report.

(2/13/1941) Re-examination - Mae T. Gandolfo owner.

Brick construction. Fair construction & repair. Age - 25 years. No parapet walls. Wood finish cornice - not cut at division wall. Hipped, slag roof. Ceilings & partitions - plaster / lath. Joist floors. Stairs - open. Heating - stoves - oil, gas, coal - safe. Cooking - coal, gas - safe. Lighting - electric, Gas - brackets, swinging - dangerous. Ashes kept outside. Waste / rubbish removed properly. Risk - Fair/poor.

No furnace. Front: One negro apartment on first floor. Coal stove kitchen. Coal stove bed room 2nd floor - Negro apartment 3rd floor - vacant apartment 3 1/2 floor - vacant rooms

Rear: 2nd floor - Gas range, oil lamp. Small oil stove. Portable gas heater. Negro apartment. 3rd floor - vacant apartment

In the second floor rear apartment there is a swinging gas bracket in the kitchen and one in the bedroom. These fixtures should be replaced by an approved rigid type gas fixture.

The housekeeping in all of the occupied apartments is of the usual negro untidy type.

3 tenants.

Exposures - similar negro apartments and small stores.

Building TypeResidenceBuilding MaterialBrickBuilding ID114Dimensions18'x# of Floors3.5Floor #Floor_IDBuilding Description

Contributing a Policy #	n Historic Pr 22265	eservation l	Perspective to the <i>Mapping the D</i> Philadelphia Contributionship	u Bois Philadel Policy Date		Property ID 64	
Address	429		S. 8th Street			Floorplan	
Owner Name	Louis J. Gan	dolfo					
Notes	#429 South 8t	h St. Being th	e Ne Corner of Lombard St. Phila. Pa.				
						oof. Ceilings & partitions - plaster / lath. h. Waste & rubbish removal - fair. Risk	
	All have hot a Vacant buildin		range.				
	Owner expects to spend at least \$2000. Bulk window in 1st for a store and a dwelling rear of 1st and above. Tenant might rent some rooms on upper floors. No tenant in prospect as yet.						
	(12/26/1940) Re-examination - Mae T. Gandolfo owner (with photos)						
	partitions - pla	ster / lath. Joi	pair. Age 125 years. No parapet walls. ist floors. Stairs - open. Heating - hot ai Waste & rubbish removal - fair. Risk - f	r, stove - safe. Coo			
	There are about The hallways	ut two cubic y have been rec	protection to the front and all sides of t rards of dirt and rotted wood on the floo ently painted, and cheap bathrooms inst ond floor front apartnemtn was open, b	r of the rear basem alled in each floor	nent. which owner stated was	s a recent innovation.	
	(2/11/1041) E	xposures: Stor	Shoemaker - white) res & Negro apartments. Floor protectio ar, which is now very tidy. The chimne				
Building Type	Multi-use		Building Material Br	ick		Building ID 115	
Dimensions	18'x31		# of Floors 3.5				
Floor	r# 1	Floor_ID	Building Description				
Cellar	3	365	(12/26/1940) Re-examination				

Hot air furnace for shoemaker shop

1	366	(12/26/1940) Re-examination	-		
		Shoemaker shop. No machinery			
2	367	(12/26/1940) Re-examination			
		Apartment vacant - N.A. Access vacant			
3	368	(12/26/1940) Re-examination			
		Apartment - Negro tenant 1 small cooking stove 1 oil lamp			
3.5	369	(12/26/1940) Re-examination			
		Apartment - Negro tenant			
Building Type	Piazza	Building Material Brick		Building ID	116
Building Type Dimensions	Piazza 14'x41'	Building Material Brick # of Floors 3		Building ID	116
				Building ID	116
Dimensions	14'x41'	# of Floors 3		Building ID	116
Dimensions Floor #	14'x41' Floor_ID	# of Floors 3 Building Description		Building ID	116
Dimensions Floor #	14'x41' Floor_ID	<i># of Floors</i> 3 Building Description (12/26/1940) Re-examination		Building ID	116
<i>Dimensions</i> <i>Floor #</i> Cellar	<i>14'x41'</i> <i>Floor_ID</i> 370	# of Floors 3 Building Description (12/26/1940) Re-examination No furnace		Building ID	116
<i>Dimensions</i> <i>Floor #</i> Cellar	<i>14'x41'</i> <i>Floor_ID</i> 370	# of Floors 3 Building Description (12/26/1940) Re-examination No furnace (12/26/1940) Re-examination Coal range.		Building ID	116
<i>Dimensions</i> <i>Floor #</i> Cellar 1	<i>14'x41'</i> <i>Floor_ID</i> 370 371	# of Floors 3 Building Description (12/26/1940) Re-examination No furnace (12/26/1940) Re-examination Coal range. Apartment - Negro tenant		Building ID	116
<i>Dimensions</i> <i>Floor #</i> Cellar 1	<i>14'x41'</i> <i>Floor_ID</i> 370 371	 # of Floors 3 Building Description (12/26/1940) Re-examination No furnace (12/26/1940) Re-examination Coal range. Apartment - Negro tenant (12/26/1940) Re-examination Bed rooms of first floor tenant. 		Building ID	116

Building Type	Residence		Building	Ma	terial	Brick	Building ID	118
Dimensions	7'x14'		# of Floo	rs	2			
Floor #	F	loor_ID	Building Descript	ion				

Contributing a	n Historic P	reservation]	Perspective to the Mapping the Di	ı Bois Philade	lphia Negro Projec	t	
Policy #	6464	Insurer	Franklin Fire Insurance Company	Policy Date	1/24/1846	Property ID	65
Address	511		S. 8th Street			Floorplan	
Owner Name	Alexander L	Reid					
Notes	Plan included	d. Plan indicate	es vacant lot to the North.				
	buildings all cased frames	lathed and plas	joists Carolina pine floor boards through stered. Reveal window frames front, mar nutters first and Venetian to second and th it.	ble sills, panel sh	utters to first and secor	nd stories and Vene	tian to third story,
Building Type	Resident	ce	Building Material Bri	ck		Building ID	19
Dimensions	18'x32'		# of Floors 3				
Floor	•#	Floor_ID	Building Description				
1		55	The first story is in one room entry off the who light 10 by 20 windows front recessed to floo doors and windows, plank double worked part and center piece in back room, story 11 ft 6 in and ornamental brackets in the back part of t	r and paneled below ssage doors, washb n high in the clear. A	w and 1 12 by 20 window ooard, neat white marble p	back the same, pilast ilaster mantel stucco	ers with fretts to cornice mouldings
2		56	The second story is in 2 rooms entry off the b and 1 10 by 18 ditto back, plain pilasters and marble mantel and 1 closet in the front room	washboard, plank of	double worked passage do	oors, 5/4 single worke	ed closet doors, plain
3		57	The third story isin 2 rooms entry and garret s 1/4 inch grecian ?? Mouldings, washboard, s closet doors 8 ft 6" story. A flight of square st and a closet underneath.	ide closet in ront an	d 2 closets in back room,	plank double worked	passage 5/4 single
Garrett		58	The garrett is in 2 rooms, a 12 light 10 by 12 panel doors and a closet in front room.	pediment top dorme	er window front and ridge	top ditto in back. Mou	ldings, washboard,
Roof		161	Cedar shingles on the main building. Tin gutt gutter is formed in the eave.	ers and conductors	, trap doors and ladders. I	Double pitch roof abou	ut 1/3 pitch, the front
Cellar		198	A furnace in the cellar which appears safe a	nd gas pipes indrod	uced into the building.		

Contributing an Historic Preservation Perst	pective to the Mapping the Du Bois Philadelphia Negro Project

Building Type	Piazza	Building Material	Brick	Building ID 34
Dimensions	8'6"x13'4"	# of Floors 3		
Floor #	Floor_ID	Building Description		
1	101	the first story. The stairs are continued	/ 14 ditto over the landing and a door frame with rail, heart steps and sizes, windows and square newell post first floor, open string, closet under	e step & landings, turned ballusters,
Roof	162	White pine shingles on the Piazza and	back building. Piazza roof is a continuation of the	he back roof
Building Type	Residence	Building Material	Brick	Building ID 46
Dimensions	13'4"x23'	# of Floors 3		
Floor #	Floor_ID	Building Description		
1	125	and panel door and 2 12 light 10 by 14 cooking range, plank double worked pa	e at rear. The first story of the back building is t windows 3 1/4 grecian ?? Mouldings, washboa assage and single closet and stair doors, a dum quare steps and winder to the second of heart	ard, large dresser with doors and drawers, nb waiter to second story, sink and story 8 ft 3
2	126	to floor and paneled below with pilaster closet and dumb waiter, stucco cornice	room off back. 3 12 light 10 by 16 windows from to door and windows same as the second stor plank double worked passage door, story 9ft 5 y 12 window in the east end, a water closet in b	ry front house, plain marble mantel, side 5in high in the clear, 2 doorways east end
3	127	The third story is in 2 rooms, 3 12 light grecian ?? Moulding and washboard.	10 by 12 windows, 8 ft 2 in story. Double worke	ed passage doors and single closet doors,
Roof	163	White pine shingles on the Piazza and	back building	

Contributing a	n Historic I	Preservation	Perspective to the Mapping the I	Du Bois Philadelphia Negro Project	
Policy #	6691	Insurer	Franklin Fire Insurance Compar	y Policy Date	Property ID 66
Address	513		S. 8th Street		Floorplan
Owner Name	Francis Mc	???			
Notes	Drawings in	cluded in surve	y. Difficult legibility - poor quality xet	rox or original?	
	Marble ?? T	o back ?? Fram	ed. Reveal window frames front with	buildings all lathed and plastered marble was marble sills, framed shutters first and second and third stories, ?? All double hung.	ater table ?? Steps and platform front. d stories and Venetian to third story
Building Type	Residen	nce	Building Material B	Prick	Building ID 20
Dimensions	18'x32'		# of Floors 3		
Floor	•#	Floor_ID	Building Description		
1		59	it. A square head front doorway with panel head, moulded caps and cornices to it and	whole depth a vestibule entry with transom lights door, transom light of glass and outside marble f 2 12 light 10 by 20 window front and 1 12 by 20 hboard, neat white marble pilaster mantel, plank 11 ft 4 in high in the clear.	rontspiece with plain pilasters, square ditto back all ?? ?? And panelled below,
2		60	paneled below, plain pilasters to ?? And w	e back rooms 2 12 light 12 by 20 window front an vindows ?? Double worked passage and 5 /4 sing ?? In front and 2 closets in back room. Stucco co	le worked closet doors. Neat white
3		61	3 1/2 grecian ?? Moulding, washboard woo	rett stairs off the back room, 2 12 light 13 by 13 v od pilaster mantel back room 1 closet in the front set doors, steps ?? 2 flight of square steps to the der the string and closet underneath.	and 2 closets in the back room. Plank
Garrett	t	62	The garret is in 2 rooms, 12 light 10 by 12 door and ladder.	light pediment top dormer ?? And a ridge top bac	k side closet back room, panel door. Trap
Roof		164	Cedar shingles on roofs wood eave and co about 1/3 pitch and the front gutters tinned	prnice front and plain brick eaves back. Tin gutter	s and conductors. Double pitch roof
Cellar		199	A furnace in the cellar for warming the hou	se and which appears to be safe. Gas piped ??.	

Page 74 of 94

Contributing an Historic Preservation Pers	pective to the <i>Mapping the Du Bois</i>	<i>Philadelphia Negro</i> Project

Building Type	Piazza	Building Material	Brick	Building ID 35
Dimensions	8'6"x13'3"	# of Floors 3		
Floor #	Floor_ID	Building Description		
2	102	the first story. The stair are continued r	st and second landing a door frame with square hea ail and heart step risers winders and square steps, d under string and a closet underneath, mahogany	2 landings, turned ballusters, a large
Roof	165	Piazza roof is continuous of the back ro	pof	
Building Type	Residence	Building Material	Brick	Building ID 47
Dimensions	13'3"x22'6"	# of Floors 3		
Floor #	Floor_ID	Building Description		
1	128	washboard, a large dresser with doors passage through closet door. A flight o	a plain back door frame and 2 12 light 10 by 14 wir and drawers, mantel shelf, sink, kitchen range, 8 ft f winding and square steps to second story has 2 1 nd windows, plank passage door, black and gold n ntry from courtyard.)	3 in story, plank double door worked 2 light 10 x16 windows recessed to floor
2	129	door, black & gold marble pilaster man	windows recessed to floor and paneld below, pilas tel, recess closet stucco cornice & 9ft 3in story, 2 d ows with Venetian shutters, ?? Weatherboards. Ro	oorways ?? ?? into a frame bath house
Roof	166	Single pitch roof to back building about	4 ft 6 in pitch	

Contributing	an Histori	c Preservation l	Perspective to the Mapping	the Du Bois Philadelphia Negro Project		
Policy #	6011	Insurer	Mutual Assurance	Policy Date	Property ID 67	7
Address	515		S. 8th Street		Floorplan	
Owner Nam	e					
Notes						
Building Typ)e		Building Material		Building ID	
Dimensions			# of Floors			
Flo	o r #	Floor_ID	Building Description			

Contributing	an Historic Preservation	Perspective to the Mapping the D	u Bois Philadei	lphia Negro Project			
Policy #	10636 Insurer	Philadelphia Contributionship	Policy Date	11/9/1906	Property ID	68	
Address	517	S. 8th Street			Floorplan		
Owner Name	e Percival E Yoder						
Notes	Brick construction. Fair construction, good repair. Age - about 60. Brick division. Cornice - wood finish, not cut at division wall. Roof - hipped tin. Ceilings plaster / lath. Floors - joist. 2 stairs - open. Heating - hot water stove, Rubber hose, safe. Lighting - gas, safe.Boiler - in building. Ashes kept outside. Waste & rubbish kept outside. Risk - excellent, except proximity to stable, where an auto car is to be stored, Frame shed between house and stable (about 12'). 2 large & 2 small windows in stable. 2 stalls baled hay in loft.						
	1 Tenant Exposures: Stable & dwelling Policy continues not withstanding the storage of an automobile in the adjoining building which is not covered under this policy.						
	(3/13/1912) Re-examination - Brick construction. Fair construction, good repair. Age - about 65. Brick division. Cornice - wood finish, not cut at division wall. Roof - hipped tin. Ceilings plaster / lath. Floors - joist. 2 stairs - open & cased. Heating - hot water stove, gas, rubber hose, safe. Lighting - electric, gas, safe. Ashes kept outside. Waste & rubbish removed properly Risk - fair. Frame shed between house and stable (about 12'). 2 large & 2 small windows in stable. 2 stalls baled hay in loft.						
	Exposures: #519 S 8th Stre Rear: Stable. Wood door op auto.	et. Milliner & Dwelling pens into this from frame shed also 2 sm	all windows in sta	ble expose shed. Now o	occupied by a carri	age and horse. No	
	(8/17/1914) House & stable	e now vacant.					

Building Type	Multi-use	Building Material Brick # of Floors 3.5	Building ID 119
Floor #	Floor_ID	Building Description	
Cellar	374	Hot water heater. Coal and gas stoves.	
1	375	Doctor's office & dwelling	
2	376	Dwelling	
3	377	Dwelling	
3.5	378	Dwelling	

Friday, August 25, 2006

Contributing a	n Historic P	reservation	Perspective to the Mapping the D	u Bois Philade	lphia Negro Project		
Policy #	3700	Insurer	Franklin Fire Insurance Company	Policy Date	9/16/1841	Property ID	69
Address	519		S. 8th Street			Floorplan	
Owner Name	Richard We	st					
Notes	Window fran shutters ?? F	ned ?? Marble	joists, Carolina heart pine floorboards, s sills, pannel shutters to first and second stories, sash all double hung, marble w re head, cornice and ??, neat wood eave	stories, Venetian s ater table, ?? Steps	shutters to the third story s and platform front, ma	y, cased window f rble frontspiece to	frames back, panel o front door, plain
Building Type	Residen	ce	Building Material Br	ick		Building ID	21
Dimensions	17'10"x.	36'	# of Floors 3				
Floor	•#	Floor_ID	Building Description				
1		63	The first story is in one room. Entry off the w ?? 12 lights 10 by 20 window front and a 16 turned block, washboards, 2 plain pilasters of cornice, mouldings and center pieces, 2 nea high, a vestibule in entry with pannel door si	light twin 16 by 20 d or ?? With ?? Caps s t white Italian marble	itto back all recessed to floo supporting a ?? Entablature e mantels, plank double wor	or and panneled bell in the center of the	ow, pilaster with room, stucco
2		64	The second story is in 2 rooms entry off bac window back not recessed to floor, pilasters stucco cornice, nead wood pilaster mantel e	with blocks, washbo	ard, 6/4 double worked doo		
3		65	The third story is in 2 rooms. Entry and garry rooms, neat wood mantel each room, ?? Mo stairs to garret, heart steps and risers, cherry	uldings 5/4 square f	ramed doors, washboard, s	tory 8 ft 10 in high, a	
Garrett		66	The garrett is in 2 rooms, square framed doo top ditto back. Trap door and ladder.	or, washboard, a 12	light 10 by 12 pediment top	dormer window fror	nt and a plain ridge
Roof		167	Cedar shingles on roof, tin gutters and cond	uctors. Double pitch	roof about 1/3 pitch.		
Cellar		200	A furnace in the cellar which appears safe.				

e on and whing white			<u>j</u>
Building Type	Piazza	Building Material Brick	Building ID 36
Dimensions	8'x16'	# of Floors 3	
Floor #	Floor_ID	Building Description	
1	103	A 12 light 10 by 13 window in the thrid story. A 10 by 16 ditto in the second stor in the first story of the Piazza. Continued rail stairs from the first to third floor he newell post first floor, mahogany moulded raile turned ballusters, open string, 2 plain flight of cellar stairs.	eart steps and risers, a large turned mahogany
Roof	168	A valley back (off the front bldg) with the piazza roof which is single pitch about	3 feet pitch
Building Type	Residence	Building Material Brick	Building ID 48
Dimensions	13'x24'	# of Floors 2	
Floor #	Floor_ID	Building Description	
1	131	The first story of the back building is in 2 rooms, Kitchen and washhouse. 2 12 drawers, mantel shelf and brackets, ?? In the ??. Single worked door and 8 fee plain back door frame and mantel shelf in the wash house and story 7 feet 2 in	of 6 in story in the kithcen, 1 window the same and a
2	132	The second story is in 3 rooms, a sitting room over the kitchen and bath and ?? the south ?? And 1 back ??, grecian ?? Mouldings, washboard, ?? For the sitti feet high. Large boards and back boards	
Roof	169	Rough pitch roof at 4 feet pitch	

Contributing a	n Historic Pre	eservation F	Perspective to the Mapping the	Du Bois Philade	lphia Negro Project	
Policy #	12455	Insurer	Franklin Fire Insurance Compa	ny Policy Date	10/2/1830	Property ID 70
Address	521		S. 8th Street			Floorplan
Owner Name	John Allen					
Notes	A Three story in the City of F		g house, piazza and two story back b	uilding situate on the	East side of Eighth Str	reet beginning ?? North of Cedar Street
	over the heads double hung, 1	, cased windo 3&9 inch wa	e floorboards, stud partitions and bui w frames back, panel shutters first ar lls, marble water table, asler, steps ar oor quality copy or original? Legibili	nd second stories from ad platform ??	nt and back and Venetia	
Building Type	Residence	2	Building Material	Brick		Building ID 67
Dimensions	17'9"x36'		# of Floors 3			
Floor	# I	Floor_ID	Building Description			
Cellar	2	36	Furnace in cellar and gas pipes introduce	d		
1	2		The First story is in one room entry off a s and 2 12 light 10 by 20 windows front rec caps & square head to doors & windows, marble ?? Mantels, stucco cornices, mou and Venetian doors to it near the front do	cess'd to floor and pane displayed jambs, wash ldings & 2 centre piece	eld below and a 16 light twi boards, plank double work	ed passage doors, 2 black and gold
2	2	38	The Second story is in 2 rooms entry off t recessed to floor and panel'd below displa not ?? 6/4 double worked passage and si Cornice and 10ft 4in story	ayed jambs, wood pilas	ter mantel each room, a 12	2 light 12 by 18 window in the back room
3	2	39	The Third story is in 2 rooms entry and ga mantel and side closet in each room, 3 in doors, 8ft 9 story, a flight of straight stairs	grecian ?? Mouldings,	washboard, 5/4 double wo	orked passage and single worked closet
Garrett	2	40	The Garrett is in 2 rooms a 12 light pedim	ent top dormer window	r front 10 by 13 glass and a	a ridge top ditto in back,

Page 80 of 94

Roof	241	Double pitch roof 1/3 pitch, wood eave cornice & dentils front and pla with back eave, single pitch roof, cedar shingle roofs tin gutters and	in brick eave back; a valley with piazza roof and eave on a line conductors
Building Type	Piazza	Building Material Brick	Building ID 68
Dimensions	8'x16'	# of Floors 3	
Floor #	Floor_ID	Building Description	
1	242	A door frame with segment top sash and side lights in the first story, and eave on a line with back eave, single pitch roof, cedar shingle ro eave on a line with back eave, single pitch roof, cedar shingle roofs to newell post mahogany rail, heart steps, turned ballusters, paneld boa	ofs tin gutters and conductorsa valley with piazza roof and in gutters and conductorsring, ?? Nosings, turned mahogany
2	243	A 12 light 10 by 16 window in the second	
3	244	A 12 light 10 by 13 window in the third story	
Roof	245	A valley with front bilding roof and eave on a line with back eave, sing	gle pitch roof, cedar shingle roofs tin gutters and conductors
Building Type	Residence	Building Material Brick	Building ID 69
Dimensions	13'3"x24'	# of Floors 2	
Floor #	Floor_ID	Building Description	
1	246	The First story of the back building isin 2 rooms dining room and kitcl Moulding, washboard, 6/4 double worked passage doors, 8ft 6 story, underneath, the kitchen has an addition addition added to it 2 12light dresser with doors & drawers, grecian ?? Mouldings washboards, iro	a flight of winding stairs in circular end and closet 10 by 14 windows and plain door frame with panel door,
2	247	The Second story has a smell room and a bath room off over the kitc ?? Mouldings washboards, closet in circular end over the stairs, nich doors, stucco cornice and 9 ft story, 1 window in the small room, the	e for store, single worked closet & double worked passage
		with lead and clode water introduced	

Page 81 of 94

Contributing an l	Historic Preservation	Perspective to the Mapping	he Du Bois Philadelphia Negro	Project
Policy # 4	256 Insure	Pennsylvania Fire	Policy Date 9/28/1841	Property ID 71
Address 5	25	S. 8th Street		Floorplan
Owner Name T	homas M Linnard			
Notes C	ancelled 15 Sept 1903 #4	4257. Floorplan included		
Building Type	Residence	Building Material	Brick	Building ID 22
Dimensions	17.5'x36'	# of Floors 3		
Floor #	Floor_ID	Building Description		
1	67	and (transom sash?) door planks. Th 10"x20" glass shutters / plank - backs resurvey) - The 1st story of Main Buil ?? window has one light of glass in fr pair of folding entrance doors, 2 lights	he first story is in one roor - has 2 windows 12 a framed and ?? ?? To floor - 2 doors to entry ding has a store front with cornice and entab ont 7'8" by 10' one light in bevel return 2'8" b s of glass, one light transom over ?? window he ?? window. The private entrance door, 4 p	eat cornice. The door is planks with square head 2 lights 10"x20" glass. 1 twin window 16 lights y - mantels of white marble. (21 March 1878 lature extending across the entire front. The ?? y 10' and 2 lights in square return 10" by 5". A is line and ?? with narrow boards. The floor has panels, 1 light transom over, Vestibule door has 2
2	68			et - door into back room - door into entry - back narbled paneled shutters back and ront doors and
3	69			utters. 1 closet. door into entry. the back room y on 3rd story has stairs into garret. closet under
Garrett	70	Garret is in two rooms - has 2 dormer	rs 12 lights 10"x13" glass ?? headers. 3 door	rs. trap door and step ladder.
Roof	170	The roof is double pitched. cedar shir	ngles. ?? ??. ?? ?? wood cornice front. brick	eave back.
Building Type	Kitchen	Building Material	Brick	Building ID 37
Dimensions	13'x29'	# of Floors 2		
Floor #	Floor_ID	Building Description		

conditionaring un		10501 (ation)	renspective to the mapping i	ne Bu Bous I muducipina riegio Project					
1		104		he 1st story is in 2 rooms has 3 windows 12 lights 10x14 glass panelled shutters - 1 closet in circular end - door into bath room, oor into yard out of the bath room mantel wood, ?? In each room					
2		183	2nd story is in 2 rooms has 3 windows 12 lights 10x16 glass paneled shutters - door into bath room, door into entry - 2 closets - over 1 window 12 lights 10x13 in bath room with paneled shutters						
Roof		184	single pitched - cedar shingles, tin shi	ngle pitched - cedar shingles, tin shutters?? Tin conductor, brick eave, Floors Carolina Pine throughout the house					
Building Type	Piazza		Building Material	Brick	Building ID 49				
Dimensions	7.5'x16	1	# of Floors 2						
Floor #	r	Floor_ID	Building Description						
1		133		ndows 12 lights 10"x14" glass panelled shutters - 1 clc room - mantels wood. ?? In each room.	oset in circular end - door into wash				
2		134		ws 12 lights 10"x16" glass panelled shutters - door into ss in bath room with panelled shutters. floors Carolina					
Roof		171	Single pitched - cedar shingles - tin sl	nutters shingled in tin conductor - brick eave					
	5803 527	Insurer	Mutual Assurance S. 8th Street	Policy Date	Property ID 72 Floorplan				
Building Type Dimensions			Building Material # of Floors		Building ID				
Floor #	r	Floor_ID	Building Description						

		n Perspective to the Mapping	the Du Bois Philadel	<i>phia Negro</i> Project		
Policy # 1	0810 Insure	r Pennsylvania Fire	Policy Date	3/25/1851	Property ID	73
Address 4	04	S. 8th Street			Floorplan	
Owner Name J	ames B Ferree					
Notes V	Vest side of 8th street 36	feet westward from Lombard - Po	licy cancelled May 2 190	5 - Jas Malatesta - 404 S	S 8th St	
Building Type	Residence	Building Material	Brick		Building ID	23
Dimensions	18'x30'	# of Floors 3				
Floor #	Floor_ID	Building Description				
1	71	The first story main house is 12 feet doorway and transom sash, a vestik pilasters and entablature and friezes entrance door 4 feet wide 9 feet hig back the same all have pannelled pl doors and windows finished with 9 in Stucco cornice pannelled ceiling and	ule ?? Feet deep and with si s, marble ?? Steps window si n, a door to the piazza back 3 ank shutters. The skirting 9 in nche double faced architrave	de lights and square transo ills and heads and ?? ?? Sa 3 by 2 feet, 2 windows front nches wide, surbase and a s ?? An ?? ?? Head to eac	om sash head, marb ash all double hung t glass 10 by 20 inch neat ?? White Italia h. Pannelled dado u	le front piece with The parlour has an nes and window In marble mantel. The
Building Type	Piazza	Building Material	Brick		Building ID	38
Dimensions		# of Floors 2				
Floor #	Floor_ID	Building Description				
1						
	105	The piazza or stairway lobby is parti 7'5" the upper story which contains the bath room, a drawing room, stor the second story a door from each h	a ?? Stairway 3 feet going ha y back. The stairway is lighte	aving 20 risers and has a ha	alf pair 16 risers hig hall. ?? 20 ?? In th	h with a door into
2	105	7'5" the upper story which contains the bath room, a drawing room, stor	a ?? Stairway 3 feet going ha y back. The stairway is lighte all. ?? Into each story a large ear has 2 rooms and an entry plain white Italian marble mar window back 9 by 18 glass a d with 6 inch double faced ar	aving 20 risers and has a has ad with a window over each e closet 4 by 4 just at the ho y partitioned from the back atel a closet in each moom all have Venetian rolling bli	alf pair 16 risers hig hall. ?? 20 ?? In the ead of the stairway. room 3 feet 6 wide a and two additional o nd shutters. The ski	h with a door into e first story. 18 in an entry door into closets in the back room rting 8 1/2 inches

Page 84 of 94

Roof	175	The loft area has a double pitch 6 feet rise to roof. Common rafters, slate ?? On lath ???? Rafters as usual, and all hemlock joist as usual throughout the house, a plain wood grecian front and brick eave back to all the back eaves.				
Building Type	Residence	Building Material	Brick	Building ID 50		
Dimensions	14'x30'	# of Floors 3				
Floor #	Floor_ID	Building Description				
1	135	the 4 window 12 lights 10 by 14 glass winding stairway at the West end lead second stofy from which a communica communicating with it is pantry finishe of the kitchen about 12 feet deep 14 ff South and is the foundation of the cor and tub and has a water closet and ?' deep 12 feet long having in front an in	pannelled shutters a dresser in the kitting to the conservatory back 2 feet 7 guttion with the drawing room. There is a d with 6 inch skirting and stucco cornic eet wide having a brick ?? One story his servatory and bath house ?? As build or ?? Railing and 3 ?? Upright tracery parts and the server price of the server price o	oom and ?? The kitchen a door in the partition between chen with drawers and doors and a common close oing 8 1/2 inch riser landing in a lobby entry in the common drawing room ?? To the kitchen e grecian moulding closet. There is a wash room back gh a door in the West ?? 8 feet high ?? A window over it and has in the bath room hydrant water fixtures ony on the south front of the conservatory 5 feet 6 bieces and has ?? Tracery ?? Under the cornice the pilasters joist off the conservatory and 3 ?? Windows		
2	136	from the conservatory with a large clo room has 3 windows 10 by 16 inches cornice centerpiece 6 inch skirting dou high has 2 rooms partitioned off comm	set and has the private stairs back of the high Venetian rolling blind shutters, a weight uble architrave trimmings and pannells nunicating door 2 closets in the middle	m called the drawing room 23 feed deep and is divided the room communicating with an entry. The drawing white Italian marble mantel 2 closetsWest end, stucco under the windows. The third story back building 8 feet room 4 windows 10 by 12 glass. ?? Blind shutters all as the latter. All the rooms plastered. Wood work all		
3	137		ly finished throughout and 6 in skirting	cating door 2 closets in the middle room 4 windows 10 a window in the West room same as the latter. All the		
Roof	176	The roof has a single pitch slate leaving	ng single pitch trap door and ladder bric	k eave cornice tin gutters and spouts		

Contributing an	Historic	Preservation	Perspective to the Mapping the Du Bois Philadelphia Negro Project
Policy #	51076	Insurer	Franklin Fire Insurance Company Policy Date 3/18/1847 Property ID 74
Address	5xx		S. 8th Street Floorplan
Owner Name	Thomas S I	Mitchell	
Notes 1	No. 277 NE	E corner of 8th a	& St. Mary's Streets. To the north, a similar three story brick house.
Building Type	Resider	nce	Building MaterialBrickBuilding ID24
Dimensions	18'x36'	,	# of Floors 3
Floor #	¥	Floor_ID	Building Description
Cellar		72	Kitchen below, plain mantel, dresser, washboards, closet and windows cased. Floor narrow heart pine boards.
1		73	The first story in 2 rooms, neat Italian Marble mantels, neat washboards, , windows cased, 1 door large folding, stucco cornices. Entry, 1 neat square head doorway with close door, square transom sash, in front is a neat flat top marble frontspiece, with plain pilasters. (Sept 8, 1886) the ?? Described building has been altered and is now a store swelling. The first story of the main house has had the floor lowered almost 2 ft, the front taken out and girder put in over door and window. A doorway with folding sash door having 1 light of sash in such ?? ?? Lights of sash overhead and an angle end bulk? Window having 1 light of sash in the front 76 by 120 inches. One light in the angle ?? 44 by 120 and 3 lights in the square ?? 8 in wide. Pilaster ?? Friezes and cornice extending across the front. Marble sill and step. A doorway to entry with panel door transom 2 lights of sash and vestibule in entry with transom 1 light and sash door to it. Part of the back window has been cut down and used as a door into the yard.
2		74	Second story in two rooms, neat mantles, washboards, closets, and windows cased. Entry halfway, washboards.
3		75	Third story in 2 rooms, plain mantles, washboards, closets and windows cased. In the entry is 1 flight close strait stairs to the garret. A large closet under.
Garrett		76	Garret in 2 rooms and plaisterd. Trap door. A semicircular window in the end, 2 neat square head dormer windows, each 12 lights glass 10x13 inches.
Roof		172	Cedar shingles, tin gutters and conductors, wood cornice front, brick back.
Building Type	Piazza		Building Material Brick Building ID 39
Dimensions	8'x16'		# of Floors 3
Floor #	ŧ	Floor_ID	Building Description

Page 86 of 94

1	108	2 flights continuous mahogany handrail stairs, plain brackets, turned ballusters and 1 flight close strait stairs to the basement story. 2 floors narrow heart other floors narrow white pine boards, glass 52 lights 12x 20, 48 ditto 12x18, 24 ditto 10x16 and 76 ditto 12x13 inches. Party walls 9 inches, stud board partitions. (March 12, 1891) A one story frame building 11 feet deep has been built on the side of Piazza enclosed with fence boards sheathed with the same, the back is covered with corrugated sheet iron. A yellow pine floor. A doorway back and sash door having 6 lights of 10x12 sash in it and wire guard to it and 24 lights of sash in ?? side having a wire screen to them.					
Roof	173	Same as house and brick cornice (March 12, 1891) tin roof with small skylight in it.					
Building Type	Residence	Building MaterialFrameBuilding ID51					
Dimensions	6'x8'	# of Floors 1					
Floor #	Floor_ID	Building Description					
1	138	At the end of the piazza and communicating is a bathhouse, 1 part brick and 3 parts frame neatly boarded, open below on 1 planed square post, ceiling plaister'd, bath room washboards, closet, window cased and plaister'd. no boiler, floor narrow heart pine boards, glass 12 lights 8x10 in. (18 March 1847) In viewing the above premises, I find there is erected at the end of and communicating with the piazza a new two story brick building 13 feet by 22 feet including the quadrant. First story in one room, a ?? Neat washboard and windows cased. A closet in the quadrant, shelv'd, washboard and windows cased. The bath house as before describ'd is now removed and attached to the end of the new building. North a two story brick building viz the frame bath on the rear has been extended out the full width of the back building and has a metal lined bathtub and a water closet placed in it hot and cold water introduced. A frame kitchen has been built under the bath house the width of the back building by 11 feet deep weatherboarded with planed boards and pinted lathed and plasterd and has a door frame outside door a window with outside shutters to it walls wainscoted 3 ft 9 in high with planed and grooved ash boards, architraves a dresser sink and single oven range.					
2	139	Second story and quadrant, finished similar to first story. Floors narrow sap pine boards, glass 24 lights 10x16 in, 24 lights 10x14 in and 4 ditto 10x12 in. party walls 9 inches.					
Roof	174	Cedar shingled roof, tin gutter and conductor. (18 March 1847) Tin roof, brick cornice					

Contributing a	an Historic Preservation F	Perspective to the Mapping the	Du Bois Philadel	phia Negro Project						
Policy #	Insurer	Philadelphia Contributionship	Policy Date	3/27/1928	Property ID 75					
Address	415	S. Perth Street			Floorplan					
Owner Name)									
Notes	415 S. Perth Street East side about 103' North from Lombard St. Researcher's Note: Photo included									
	Brick. Fair/good construction & repair. Wood finish cornice, not cut at division wall. No parapet walls. Tin & felt hipped roof. Ceilings & walls lapped plaster. Joist floors. Cased stairs. Coal cooking stove. Oil lighting. Ashes kept outside. As a whole - good/fair risk.									
	Coal stove - no floor protect 1 Family	ion								
	Exposures - Dwellings. Private garage on North									
	(Oct 16, 1947) Nos 415-17-19 Poor condition, substandard construction. Wood cornice not cut, no parapet walls Substandard construction. Poor repair. Wood cornice. Composition paper roof. Rear exposure Court Dwellings on Unity Court. Neighborhood is decadent. Not recommended for new insurance because of construction, age and location.									
Building Type	e Residence	Building Material	Brick		Building ID 105					
Dimensions		# of Floors 3								

Floor # Floor_ID Building Description

Contributing	an Historic Preservation	Perspective to the <i>Mapping the</i>	Du Bois Philadel	<i>phia Negro</i> Project	:					
Policy #	Insurer	Philadelphia Contributionship	Policy Date	3/27/1928	Property ID 76					
Address	417	S. Perth Street			Floorplan					
Owner Nam	е									
Notes	417 S Perth St East side abo	417 S Perth St East side about 90 ' North from Lombard St. For Photo see 415 S Perth St								
	Brick. Fair/good construction & repair. Brick cornice, not cut at division wall. No parapet walls. Tin & felt hipped roof. Ceilings & walls lath plaster. Joist floors. Cased stairs. Coal cooking stove. Oil lighting - safe. Ashes kept outside. Waste & rubbish removed properly. As a whole - good/fair risk.									
	Coal stove - no floor protec 1 Family Exposures - Dwellings	ction								
	(Oct 16, 1947) Nos 415-17-19 Poor condition, substandard construction. Wood cornice not cut, no parapet walls Substandard construction. Poor repair. Wood cornice. Composition paper roof. Rear exposure Court Dwellings on Unity Court. Neighborhood is decadent. Not recommended for new insurance because of construction, age and location.									
Building Typ Dimensions	e Residence 13'x20'	Building Material 1 # of Floors 3	Brick		Building ID 103					

Floor #

Floor_ID Building Description

Contributing a	n Historic Preservation	Perspective to the Mapping the	Du Bois Philadelphia Neg	ro Project				
Policy #	Insure	r Philadelphia Contributionship	Policy Date	Property ID 77				
Address	419	S. Perth Street		Floorplan				
Owner Name)							
Notes	Notes (Oct 16, 1947) Nos 415-17-19 Poor condition, substandard construction. Wood cornice not cut, no parapet walls Substandard construction. Poor repair. Wood cornice. Composition paper roof. Rear exposure Court Dwellings on Unity Court. Neighborhood is decadent. Not recommended for new insurance because of construction, age an location.							
Building Type Dimensions	Residence	Building Material # of Floors 3	Brick	Building ID 107				

Floor #

Floor_ID Building Description

Contributing a	n Historic Preservation P	Perspective to the Mapping the	Du Bois Philadel	lphia Negro Project					
Policy #	Insurer	Philadelphia Contributionship	Policy Date	3/27/1928	Property ID	78			
Address	421	S. Perth Street			Floorplan				
Owner Name									
Notes	421 S. Perth St east side abo	ut 62' North of Lombard St. Rear of	727 Lombard St (For	r photo see 417 S Perth	St)				
	Brick. Fair/good construction & repair. No parapet walls. Brick cornice, not cut at division wall. Tin hipped roof. Ceilings & walls lath & plaster. Jois floors. As a whole - good/fair risk.								
	For rent								
	Exposures - Dwellings								
	(Oct 16, 1947) No 421 Poor condition. Rear exposure Court Dwellings on Unity Court. Neighborhood is decadent. Not recommended for new insurance because of construction, age and location.								
Building Type	Residence	Building Material	Brick		Building ID	104			

of Floors 3

Floor_ID Building Description

Dimensions

Floor #

16'x30'

Contributing a	an Historic	Preservation	Perspective to the Mapping t	he Du Bois Philadel	phia Negro Project		
Policy #	1519	Insurer	Pennsylvania Fire	Policy Date	9/9/1830	Property ID	79
Address	4xx		S. Perth Street			Floorplan	
Owner Name	🗧 Joshua Tra	ivis					
Notes	Three story	brick dwelling	house and Kitchen situated on the	East side of Pleasant Av	enue. The second house	from Little Pine	St. No 2
Building Type	e Resider	ıce	Building Material	Brick		Building ID	25
Dimensions	14'x16'	,	# of Floors 3				
Floo	r #	Floor_ID	Building Description				
1		77	Sap floor. One window in front. 9x14	glass. One window in back.	8-10 glass. Panneled shutt	ers on each. A ?? c	closet. Mantle.
2		78	2nd FI - sap floor. one room with lobb	y entry. Sap floor. Closet, m	nantle, windows similar to 1	st floor. Winding sta	ir to garrett
3		79	3rd FI - similar to 2nd story				
Garret	tt	80	Garret - Sap floor. Common dormer.				
Roof		177	Broken pitch roof. cedar shingles. Wo	ood spouts			
Building Type	e Kitcher	ı	Building Material	Brick		Building ID	40
Dimensions	10'x14'	,	# of Floors 1				
Floo	r #	Floor_ID	Building Description				
Cellar		109	common rough floor. One window an	d used as a kitchen			
1		110	1st FI - two 8x10 windows. Sap floor				
Roof		178	Roof - single pitched inclining South				

Contributing a	in Historic	Preservation	Perspective to the <i>Mapping</i>	the Du Bois Philadelphia Negro Project		
Policy # Address Owner Name Notes	7554	Insurer	Mutual Assurance	Policy Date	Property ID Floorplan	80
Building Type Dimensions	,		Building Material # of Floors		Building ID	
Floo	r #	Floor_ID	Building Description			

Contributing a	n Historic H	Preservation	Perspective to the Mapping the L	Du Bois Philade	lphia Negro Project		
Policy #		Insurer	Philadelphia Contributionship	Policy Date	9/20/2020	Property ID	82
Address	714		Lombard Street			Floorplan	
Owner Name	•						
Notes	714 Lombar	d St South side	about 103' West of South 7th St Phila.	PA - For plan see	report on #710 Lombard	l St	
	plaster/lath. rubbish - fai About 4 tena Exposures - Plastering of	Joist floors. Of r. Fair/Bad risk ants Colored Lodgi ff on all floors.	nd repair. Age - 76. No parapet walls. We pen stairs. Stoves - no floor protection. It. ngs & church. Colored dwellings Bad settlement about one door ng & falling off.			-	• •
	One painted	cening blisten					
Building Type	Residen	ice	Building Material B	rick		Building ID	112
Dimensions			# of Floors 3				
Floor	r #	Floor_ID	Building Description				
Cellar		384	Coal & gas ranges. Smoke pipe has fallen	apart.			
1		385	1st Floor Beauty parlor & dwelling.				
2		386	2nd Floor - coal stove for heat				
3		387	3rd Floor - good repair				